

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/28/2022

Submitted Date:

04/29/2022

Document Number:

699105307**FIELD INSPECTION FORM**Loc ID 450201 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections
Kraich, Adam		adam.kraich@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
450207	WELL	PR	07/15/2018	OW	123-44703	Longhorn V41-10-9XRLNB	SI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment next to the ECD needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606. Submit photo with FIRR	Date:	05/06/2022
Type	TRASH		
Comment:	Trash inside tank containment needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606. Submit photo with FIRR	Date:	05/06/2022
Type	OTHER		
Comment:	Stained soil in multiple spots needs to be removed. See attached photos		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e." Submit photos with FIRR	Date:	05/06/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Bird Protectors	# 1		corrective date
Comment:	Bird protector missing on ecd. See attached photo.		
Corrective Action:	All stacks, vents, or other openings will be equipped with screens or other appropriate equipment to prevent entry by wildlife, including birds and bats per Rule 608.b.(7) Submit photos with FIRR	Date:	05/06/2022
Type: Other	#		
Comment:	Unmarked/Unused riser needs marked. See attached photo.		
Corrective Action:	Upon removing a flowline or crude oil transfer line from use with the intent to abandon, an operator must immediately apply OOSLAT to the risers. OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until the operator removes the riser. Comply with Rule 1105.b.	Date:	05/06/2022

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected FacilitiesFacility ID: 450207 Type: WELL API Number: 123-44703 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

BradenHeadDate of Last Brhd Test: 06/22/2021Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 17

Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 4/28/22 at approximately 1016hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Longhorn V41-10-9XRLNB of Civitas, at Location ID # 450201 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Trash inside tank containment needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 5/6/22</p> <p>Unused equipment next to the ECD needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 5/6/22</p> <p>Stained soil in multiple spots needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a corrective action date of 5/6/22</p> <p>Unmarked/Unused riser needs marked. Upon removing a flowline or crude oil transfer line from use with the intent to abandon, an operator must immediately apply OOSLAT to the risers. OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until the operator removes the riser. Comply with Rule 1105.b. With a corrective action date of 5/6/22</p> <p>Bird protector missing on ECD. All stacks, vents, or other openings will be equipped with screens or other appropriate equipment to prevent entry by wildlife, including birds and bats per Rule 608.b.(7). With a corrective action date of 5/6/22</p> <p>See attached photos.</p> <p>Submit pictures on FIRR.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	burnsa	04/29/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403032335	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5739058
699105308	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5739057