

TEP
Gypsum ranch A
Location # 335556



location



location

TEP
Gypsum ranch A
Location # 335556



Valve on tank actively leaking



Valve on tank actively leaking

TEP
Gypsum ranch A
Location # 335556



May 9, 2022 at 10:22:38 AM
39.526426, -107.752081 ±4.78m
OGCC

Valve on tank actively leaking



May 9, 2022 at 10:23:48 AM
39.526367, -107.751888 ±4.76m
OGCC

Follow up inspection photo

TEP
Gypsum ranch A
Location # 335556



Follow up inspection photo



Follow up inspection photo

TEP
Gypsum ranch A
Location # 335556



Follow up inspection photo



Follow up inspection photo

TEP
Gypsum ranch A
Location # 335556



Previous inspection photo



Previous inspection photo

TEP
Gypsum ranch A
Location # 335556



Previous inspection photo



Previous inspection photo