

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403053180

Date Received:
05/18/2022

FIR RESOLUTION FORM

Overall Status: FRQ

CA Summary:

1 of 6 CAs from the FIR responded to on this Form

0 CA Completed
1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Romana Cowden</u>	<u>720-951-5895</u>	<u>cogcc.inspections@caerusoilandgas.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696203710

Inspection Date: 05/16/2022 FIR Submit Date: 05/17/2022 FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 458475

Location Name: ELU Number: A24-496 Pad County: _____

Qtrqtr: Lot 4 Sec: 24 Twp: 4S Range: 96W Meridian: 6

Latitude: 39.694314 Longitude: -108.125933

FACILITY - API Number: 05-045-00 Facility ID: 458475

Facility Name: ELU Number: A24-496 Pad

Qtrqtr: Lot 4 Sec: 24 Twp: 4S Range: 96W Meridian: 6

Latitude: 39.694314 Longitude: -108.125933

CORRECTIVE ACTIONS:

4 CA# 161971

Corrective Action: Comply with 1002.c and implement BMPs to protect soil stockpiles Date: 05/24/2022

Response: FACTUAL REVIEW REQUEST

Basis for Review: Action requested was already completed prior to the inspection

Operator Comment: Topsoil has been seeded, and vegetation is starting to emerge. The temporary above-ground pipeline has been pressure tested and is sound, thus it should not damage topsoil. This line will be removed when no longer needed.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Prior to the establishment of vegetation, seeding alone is insufficient when soils are bare. Ensure BMPs are maintained in order to protect stockpiles in accordance with 1002.c and 1002.f.

COGCC Supervisor: Prior to the establishment of vegetation, seeding alone is insufficient when soils are bare. Ensure BMPs are maintained in order to protect stockpiles in accordance with 1002.c and 1002.f.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed: _____

Title: EHS

Date: 5/18/2022 12:41:36 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403053180	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files