

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/16/2022

Submitted Date:

05/16/2022

Document Number:

699105388

**FIELD INSPECTION FORM**Loc ID 332341 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272102	WELL	SI	08/01/2021	GW	123-22174	GUTTERSEN STATE CC 32-12	TA

**General Comment:**

This is a follow up to FIRR #403047373. CA was not corrected.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	Adequate
Corrective Action:	
Date:	

<b>Good Housekeeping:</b>		
Type	OTHER	
Comment:	Stained soil around the well, needs to be removed. See attached photos.	
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."	Date: 05/16/2022

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 272102 Type: WELL API Number: 123-22174 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: T/A

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 04/15/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 5/16/22 at approximately 0933hrs, I, Inspector Adam Burns, Conducted an on-site inspection to FIRR #403047373 at Gutttersen State CC 32-12 of Chevron, at</p> <p>API # 05-123-22174 in Weld County, Colorado.</p> <p>CA was not complete did not meet expectations.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Stained soil around the well, needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a corrective action date of 5/16/22</p> <p>See attached photos.</p> <p>Submit photos with FIRR</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	burnsa	05/16/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403050948	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5755226">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5755226</a>
699105389	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5755218">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5755218</a>