

Inspection Photos
Operator: Kinder Morgan
API: 033-06183
Date: 5/20/2022



Photo 1. View from the end of the access road facing southeast, toward former well pad area.



Photo 2. View of remaining access road facing northward.



Photo 3. View of culvert outlet along the access road where sediment is accumulated and is overflowing silt trap off and flowing offsite.



Photo 4. View of area downslope of Photo 3, showing sediment discharging downslope from culvert outlet.



Photo 5. View of another culvert outlet along the access road that is full of sediment and is not an adequate long-term stabilization measure.