

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403062312

Date Received:
05/27/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

6 of 8 CAs from the FIR responded to on this Form

0 CA Completed
6 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

alex.fischer@state.co.us

john.heil@state.co.us

[Inspections](#)

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696203718

Inspection Date: 05/05/2022

FIR Submit Date: 05/25/2022

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 480732

Location Name: FEDERAL Number: WMC 24-17 County: _____

Qtrqr: SESW Sec: 17 Twp: 7S Range: 93W Meridian: 6

Latitude: 39.439076 Longitude: -107.799611

FACILITY - API Number: 05-045-

-00

Facility ID: 480732

Facility Name: FEDERAL Number: WMC 24-17

Qtrqr: SESW Sec: 17 Twp: 7S Range: 93W Meridian: 6

Latitude: 39.439076 Longitude: -107.799611

CORRECTIVE ACTIONS:

2 CA# 162271

Corrective Action: Comply with 1002.f and install or maintain stormwater and erosion control BMPs in accordance with good engineering practices.

Date: 06/01/2022

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Inspection was conducted on May 5, 2022. The FIR was received on May 25, 2022. There is not sufficient time

Operator Comment: to complete the CA by the June 1, 2022 due date. An email was sent to Inspector Trujillo on May 26, 2022 providing details and is attached.

COGCC Decision: _____

COGCC Representative: _____

3 CA# 162272

Corrective Action: Comply with 1002.f and install or maintain stormwater and erosion control BMPs in accordance with good engineering practices.

Date: 06/01/2022

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: Inspection was conducted on May 5, 2022. The FIR was received on May 25, 2022. There is not sufficient time to complete the CA by the June 1, 2022 due date. An email was sent to Inspector Trujillo on May 26, 2022 providing details and is attached.

COGCC Decision: _____

COGCC Representative: _____

4 CA# 162273

Corrective Action: Comply with 1002.f and install or maintain stormwater and erosion control BMPs in accordance with good engineering practices.

Date: 06/01/2022

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: Inspection was conducted on May 5, 2022. The FIR was received on May 25, 2022. There is not sufficient time to complete the CA by the June 1, 2022 due date. An email was sent to Inspector Trujillo on May 26, 2022 providing details and is attached.

COGCC Decision: _____

COGCC Representative: _____

5 CA# 162274

Corrective Action: Comply with 1002.f and install or maintain stormwater and erosion control BMPs in accordance with good engineering practices.

Date: 06/01/2022

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: Inspection was conducted on May 5, 2022. The FIR was received on May 25, 2022. There is not sufficient time to complete the CA by the June 1, 2022 due date. An email was sent to Inspector Trujillo on May 26, 2022 providing details and is attached.

COGCC Decision: _____

COGCC Representative: _____

6 CA# 162275

Corrective Action: Comply with 1002.f and install or maintain stormwater and erosion control BMPs in accordance with good engineering practices.

Date: 06/01/2022

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: Inspection was conducted on May 5, 2022. The FIR was received on May 25, 2022. There is not sufficient time to complete the CA by the June 1, 2022 due date. An email was sent to Inspector Trujillo on May 26, 2022 providing details and is attached.

COGCC Decision: _____

COGCC Representative: _____

8 CA# 162277

Corrective Action: Improper soil salvage has resulted in the loss or degradation of the topsoil resource, therefore Operator is being directed to propose an acceptable solution to the COGCC, in order to resolve the soil salvage compliance issues.

Operator shall provide solution and justifications attached to a Form 4, and submit with a request that document is routed to NW Reclamation Specialist Trujillo.

This corrective action will stand until issue has been resolved.

Date: 06/03/2022

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: Inspection was conducted on May 5, 2022. The FIR was received on May 25, 2022. There is not sufficient time to complete the CA by the June 3, 2022 due date. An email was sent to Inspector Trujillo on May 26, 2022 providing details and is attached.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: COGCC conducted a site inspection on May 5, 2022. The FIR was received by TEP on May 25, 2022. Corrective due dates for June 1 and 3, 2022 are not attainable. See attached email dated May 26, 2022.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Environmental Lead

Date: 5/27/2022 10:33:18 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403062321	Correspondence
403062324	Correspondence
403062325	WMC 24-27 Erosion Control Plan

Total Attach: 3 Files