

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/17/2022

Submitted Date:

05/23/2022

Document Number:

702800238**FIELD INSPECTION FORM**Loc ID 428856 Inspector Name: O'Malley, Anna On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10396Name of Operator: SWN PRODUCTION COMPANY LLCAddress: P.O. BOX 12359City: SPRING State: TX Zip: 77391-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pate, James		jspconcrete@yahoo.com	Principle Agent
Stepp, Sarah		wcciassistant@gmail.com	All Inspections
, SWN		swnsandwash@swn.com	All Inspections

**General Comment:**

On 05/17/2022, Reclamation Specialist O'Malley conducted a reclamation and stormwater inspection at Beeman Oil & Gas LLC's Simoes /22-30 Location #428856 in Moffat County, Colorado.

The following compliance issues were observed during this inspection:

- Location signage with incorrect Operator information
- Weed debris
- Unused equipment
- Noxious weeds: houndstongue, toadflax, thistle spp.
- Stormwater: erosion of cut slope

Refer to the "Location," "Reclamation," "Stormwater" and "COGCC Comments" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

COGCC records show the Operator for this Location as SWN Production Company LLC #10396. Form 09 (S) #403026381 to transfer Operatorship from SWN Production Company LLC to Beeman Oil & Gas LLC is in process. Until COGCC records show Beeman Oil & Gas LLC as the Operator, both Operators are included in inspection reports.

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Signage at the wellhead reads with incorrect Operator information.		
Corrective Action:	Comply with 605 Rules- implement signage with correct Operator throughout Location.	Date:	06/29/2022

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Weed debris was observed accumulating throughout the production area including around production equipment. Seedlings of the undesirable plant species/weed kochia were observed throughout the Location and will contribute more weed debris to the Location in the future.		
Corrective Action:	Comply with Rule 606.	Date:	05/30/2022
Type	UNUSED EQUIPMENT		
Comment:	It was observed in this inspection that unused equipment, piping etc. was stored on the production area.		
Corrective Action:	Comply with Rule 606.	Date:	06/07/2022

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_



TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation

Well Release on Active Location ☐Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: It was observed in this inspection that stormwater and sediment control BMPs are missing or insufficient on the cut slopes of the Location; the cut slope to the west of the Location is largely unprotected. It is sparsely colonized by annual noxious weeds which do not stabilize soils and must be removed. Perennial grasses are sparse and insufficient to stabilize the slope. Pedestals are present due to stormwater degradation. Pedestals form when stormwater erodes away un-stabilized areas of soil around vegetation. Additionally, the slope is undercutting at the top, resulting in exposed roots and vegetation and soil degradation in the area above the cut.

Corrective Action: Install or repair required BMPs per Rule 1002.f. Continue to monitor and manage stormwater on the Location. Ongoing stormwater management is required until the site receives a passing final inspection.

Date: 06/22/2022

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Note to Operator: nesting bird present at the southern edge of the production pad. See attached photos for Location. BMPs to avoid disturbing the nest are advised.	omalleya	05/23/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403056486	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5760477">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5760477</a>
702800239	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5760469">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5760469</a>