

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/31/2022

Submitted Date:

06/01/2022

Document Number:

690202968

**FIELD INSPECTION FORM**

Loc ID 481116 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10767  
Name of Operator: TWIN BRIDGES RESOURCES LLC  
Address: 475 17TH ST., STE 900  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 8 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name   | Phone | Email                        | Comment |
|----------------|-------|------------------------------|---------|
| Kosola, Jason  |       | jason.kosola@state.co.us     |         |
| ROGOWSKI KELLY |       | krogowski@twinbridgesllc.com |         |
| WALLACE TOM    |       | tcw@twinbridgesllc.com       |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name   | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 481333      | WELL | DG     | 04/02/2022  |            | 071-09919 | Red Rocks 35-15 | RI          |

**General Comment:**

This is a Location Construction Inspection. The well was drilled as of 4/2/2022.  
See attached photos and additional details within this report.

**Location**

Overall Good:

**Signs/Marker:**

|                    |   |       |  |
|--------------------|---|-------|--|
| Type               | WELLHEAD  |       |  |
| Comment:           | Sign posted at wellhead and entrance of location. |       |  |
| Corrective Action: |   | Date: |  |

**Emergency Contact Number:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Comment:           | <input type="text"/> | Date: |  |
| Corrective Action: | <input type="text"/> | Date: |  |

**Good Housekeeping:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | OTHER   |       |            |
| Comment:           | The wellhead cellar needs to be covered to prevent livestock/wildlife entry.  |       |            |
| Corrective Action: | Comply with 602.c.  | Date: | 06/08/2022 |
| Type               | STORAGE OF SUPL   |       |            |
| Comment:           | There is equipment being stored near the location which will need to be removed. Equipment storage will create additional disturbance. Associated disturbance will need to be reclaimed. Vehicles and equipment shall not travel outside of original access road and location boundary. |       |            |
| Corrective Action: | Comply with Rule 606  | Date: | 06/30/2022 |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Location Construction**

Location ID: 481333 CDP: \_\_\_\_\_

**Comment:** There was no form 42 Notice submitted for Construction. Operators will provide the Commission written notice 2 business days in advance of commencing construction or a major change at any Oil and Gas Location or Oil and Gas Facility. Operator did not comply with Rule 405.b.

**Corrective Action:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Form 2A COAs:**

**Comment:** \_\_\_\_\_

**Corrective Action:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**Comment:** \_\_\_\_\_

**Corrective Action:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

| Erosion BMPs | Present | Other BMPs | Present |
|--------------|---------|------------|---------|
|              |         |            |         |

**Comments:** Erosion BMPs: The straw wattles are not properly installed and do not completely protect down gradient runoff from disturbed areas.

Other BMPs: \_\_\_\_\_

**Corrective Action:** Install or repair required BMPs per Rule 1002.f.(2)C **Date:** 06/08/2022

2

**Comment:** There are multiple soil piles on location. Soil piles need to properly marked and stored. Soil piles need to be protected and stabilized per Rule 1002.c.

**Corrective Action:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Environmental**

**Waste Management:**

| Type              | Management   | Condition  | GPS (Lat) | (Long)           |
|-------------------|--|------------|-----------|------------------|
| Drill Cuttings    | Piles  | Inadequate |           |                  |
| Comment           | There are multiple piles on location which at least one pile may be drill cuttings. There has been no form 27 submitted for burial in a Cuttings Trench and there are piles sitting on the soil surface with inadequate stormwater protection. |            |           |                  |
| Corrective Action | Comply with 905.g. COGCC EPS staff (Jason Kosola) for directives.  |            |           | Date: 06/02/2022 |

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB):

Comment:

Pilot:  Wildlife Protection Devices (fired vessels):

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 690202969    | Inspection Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5767694">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5767694</a> |