

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403067714

Date Received:

06/03/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10661

Name of Operator: BISON OIL & GAS II LLC

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Mike Storey

970-939-6353

mstorey@civiresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696304235

Inspection Date: 05/31/2022

FIR Submit Date: 05/31/2022

FIR Status: _____

Inspected Operator Information:

Company Name: BISON OIL & GAS II LLC

Company Number: 10661

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 454166

Location Name: Hunt 8-60 Number: 6C County: _____

Qtrqr: Lot 7 Sec: 6 Twp: 8N Range: 60W Meridian: 6

Latitude: 40.687550 Longitude: -104.141661

FACILITY - API Number: 05-123-00 Facility ID: 454166

Facility Name: Hunt 8-60 Number: 6C

Qtrqr: Lot 7 Sec: 6 Twp: 8N Range: 60W Meridian: 6

Latitude: 40.687550 Longitude: -104.141661

CORRECTIVE ACTIONS:

1 ☒ CA# 162352

Corrective Action: Comply with Rule 606

Date: 06/03/2022

Response: CA COMPLETED

Date of Completion: 06/03/2022

Operator Comment: Risers have been marked in compliance with Rule 606.

COGCC Decision: Approved

Approved

COGCC
Representative:

2 ☒ CA# 162353

Corrective Action: For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."
Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 06/03/2022

Response: CA COMPLETED

Date of Completion: 06/03/2022

Operator Comment: Stained soil has been removed per Rule 905.e, All valves have been securely fastened per Rule 608.e.

COGCC Decision: Approved

COGCC
Representative: Approved

3 ☒ CA# 162354

Corrective Action: Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 902.b
For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."

Date: 06/07/2022

Response: CA COMPLETED

Date of Completion: 06/03/2022

Operator Comment: Wildlife protection equipment has been installed in compliance with Rule 902.b, Oily waste has been removed in accordance with 905.e

COGCC Decision: Approved

COGCC
Representative: Approved

4 ☒ CA# 162355

Corrective Action: Comply with Rule 606
Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) per Rule 902.b

Date: 06/07/2022

Response: CA COMPLETED

Date of Completion: 06/03/2022

Operator Comment: Wildlife protection equipment has been installed in compliance with Rule 902.b

COGCC Decision: Approved

COGCC
Representative: Approved

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Aubrey Noonan

Signed: _____

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403067714	FIR RESOLUTION SUBMITTED
403067719	Inspection Photos

Total Attach: 2 Files