

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/05/2022

Submitted Date:

06/07/2022

Document Number:

699700315**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
 _____ Heil, John _____ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Gardner, Mike		mgardner@terraep.com	

General Comment:

On May 5, 2022, COGCC Environmental Staff (John Heil) conducted an environmental field inspection of TEP ROCKY MOUNTAIN LLC (TEP operator #96850) 4-inch flex-pipe produced water line associated with Spill/Release ID 482164.

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 100

Comment: 5/5/2022 COGCC staff conducted a visual inspection of the spill/release area, as well as the adjacent impacted Black Sulfur Creek. An excavation containing the ruptured 4-inch flex-pipe produced water line was observed measuring approximately 25'x10'x6' (LxWxH). The excavation was fenced and contained potentially impacted material as well as potentially impacted fluids. Various sized stockpiles of potentially impacted material were located on the east and west side of the excavation and had a detectable hydrocarbon odor at time of inspection. COGCC staff observed what appeared to be a visible sheen with a detectable hydrocarbon odor on Black Sulfur Creek adjacent to the spill/release area. The same sheen was not observed up-gradient or down-gradient of the spill/release area. Water well Permit #295154 located approximately 1 mile upstream on Black Sulfur Creek reports a static water level of 12.68 feet. See Photo Log for details.

Corrective Action: Opeator shall comply with COAs on Form 19 Doc #403039707 and #403048520.

Date: _____

Reportable: YES

GPS: Lat 39.858160

Long -108.310556

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699700316	20220505 Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5772499