

Document Number:
 402914629
 Date Received:
 01/03/2022

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 10454 Contact Name: Cal St. John
 Name of Operator: PETROSHARE CORPORATION Phone: (720) 545-5624
 Address: 9635 MAROON CIRCLE #400 Fax: _____
 City: ENGLEWOOD State: CO Zip: 80112 Email: cal.stjohn@state.co.us

For "Intent" 24 hour notice required, Name: Medina, Justin Tel: (720) 471-0006
COGCC contact: Email: justin.medina@state.co.us

Type of Well Abandonment Report: Notice of Intent to Abandon Subsequent Report of Abandonment

API Number 05-001-08480-00
 Well Name: UPRR KALCEVIC (OWP) Well Number: 33-3
 Location: QtrQtr: NWSE Section: 3 Township: 2S Range: 63W Meridian: 6
 County: ADAMS Federal, Indian or State Lease Number: _____
 Field Name: CHIEFTAIN Field Number: 11060

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.903050 Longitude: -104.421000
 GPS Data: GPS Quality Value: 5.3 Type of GPS Quality Value: PDOP Date of Measurement: 08/12/2012
 Reason for Abandonment: Dry Production Sub-economic Mechanical Problems
 Other Orphaned Well
 Casing to be pulled: Yes No Estimated Depth: _____
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
J SAND	7480	7516			
Total: 1 zone(s)					

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	UNK	24	0	222	200	222	0	VISU
1ST	7+7/8	5+1/2	UNK	17 & 15.5	0	7600	550	7600	6700	CBL
				Stage Tool	0	1184	350	1184	208	CALC

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 7405 with 3 sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
 CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set 145 sks cmt from 1234 ft. to 0 ft. Plug Type: CASING Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at 6500 ft. with 45 sacks. Leave at least 100 ft. in casing 6410 CICR Depth
 Perforate and squeeze at 2265 ft. with 50 sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 (Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged:
 Set 10 sacks at surface
 Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
 Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Number of Days from Setting Surface Plug to Capping or Sealing the Well: _____
 Surface Plug Setting Date: _____ Cut and Cap Date: _____
 *Wireline Contractor: _____ *Cementing Contractor: _____
 Type of Cement and Additives Used: _____
 Flowline/Pipeline has been abandoned per Rule 1105 Yes No

Technical Detail/Comments:
 CBL Required. Plugging procedure may be modified based on CBL cement coverage findings.
 The following are descriptions perforate and squeeze plugs with Tag requirements.
 Plug #2 - Perf at 6500' and 6400', set CICR at 6410' and pump 35 sx through CICR. Leave 10 sx on top of CICR.
 Plug #3 - Perf at 2265' and pump 40 sx through perms. Leave 10 sx inside. Tag above 2165' is required.
 Plug #4/Surface - Place 145 sx balance plug from 1234' to surface. Cement to surface.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.
 Signed: _____ Print Name: Cal St. John
 Title: OWP Engineering Tech Date: 1/3/2022 Email: cal.stjohn@state.co.us

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.
 COGCC Approved: Jacobson, Eric Date: 6/9/2022

Condition of Approval

COA Type

Description

	CBL to be run prior to plugging to verify stage tool setting depth and existing coverage - submit to COGCC for verification of plugging orders.
	<p>Prior to starting plugging operations a bradenhead test shall be performed if there has not been a reported bradenhead test within the 60 days immediately preceding the start of plugging operations.</p> <p>1) If, before opening the bradenhead valve, the beginning pressure is greater than 25 psi, sampling is required.</p> <p>2) If pressure remains at the conclusion of the test, or if any liquids were present during the test, sampling is required.</p> <p>The Form 17 shall be submitted within 10 days of the test. Sampling shall comply with Operator Guidance - Bradenhead Testing and Reporting Instructions. If samples are collected, copies of all final laboratory analytical results shall be provided to the COGCC within three (3) months of collecting the samples.</p> <p>If there is a need for sampling, contact COGCC engineering for verification of plugging procedure.</p>
	<p>1) Provide 2 business day notice of plugging MIRU via electronic Form 42.</p> <p>2) After placing the shallowest hydrocarbon isolating plug (6500'), operator must wait a sufficient time to confirm static conditions. If at any time after placing this plug there is evidence of pressure or of fluid migration, contact COGCC engineering before continuing operations.</p> <p>3) Prior to placing the 1234' plug: verify that all fluid migration (liquid and gas) has been eliminated. If evidence of fluid migration or pressure remains, contact COGCC Engineer for an update to plugging orders.</p> <p>4) After isolation has been verified, pump plug and displace. If cement is not circulated to surface, shut-in, WOC 4 hours then tag plug – must be at 172' or shallower and provide 10 sx plug at the surface.</p> <p>5) Leave at least 100' of cement in the wellbore for each plug.</p> <p>6) Properly abandon flowlines as per Rule 1105. Pursuant to Rule 911.a. Closure of Oil and Gas Facilities, Operator will submit Site Investigation and Remediation Work plans via Form 27 for COGCC prior approval before cutting and capping the plugged well, conducting flowline abandonment, and removing production equipment. Pursuant to Rule 1105.f. Abandonment Verification, within 90 days of an operator completing abandonment requirements for a flowline or crude oil transfer line, an operator must submit a Field Operations Notice, Form 42-Abandonment of Flowlines for on-location flowlines, and a Flowline Report, Form 44, for off-location flowlines or crude oil transfer lines.</p> <p>7) With the Form 6 SRA operator must provide written documentation, which positively affirms each COA has been addressed.</p>
	Operator will implement measures to capture, combust, or control emissions to protect health and safety, and to ensure that vapors and odors from well plugging operations do not constitute a nuisance or hazard to public health, welfare and the environment.
4 COAs	

Attachment List

Att Doc Num

Name

402914629	FORM 6 INTENT SUBMITTED
402914650	WELLBORE DIAGRAM

Total Attach: 2 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Engineer	Well file verification not completed prior to approval of NOIA.	01/07/2022
Engineer	Deepest Water Well within 1 Mile – 515' SB5 Base of Fox Hills - 1130' Denver 5056 5118 23.9 108 46 6.50NNT Upper Arapahoe 4855 5025 93.7 309 139 25.49NNT Lower Arapahoe 4583 4780 68.6 581 384 18.66NT Laramie-Fox Hills 4034 4244 122.9 1130 920 29.50NT	01/07/2022
Permit	-Confirmed as-drilled well location. -No other forms in process. -Production reporting delinquent. -Confirmed completed interval docnum: 346200. -Reviewed WBDs. -Pass.	01/03/2022

Total: 3 comment(s)