

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403075954

Date Received:

06/10/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87401

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Etta Trujillo

5053244154

etrujillo@logosresourcesllc.com

Vanessa Fields

5057872218

vfields@logosresourcesllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 688801146

Inspection Date: 04/11/2022

FIR Submit Date: 04/12/2022

FIR Status: _____

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC

Company Number: 10679

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87401

LOCATION - Location ID: 333532

Location Name: R&G Number: 26-3 County: LA PLATA

Qtrqr: NWSE Sec: 26 Twp: 33N Range: 7W Meridian: N

Latitude: 37.072410 Longitude: -107.573880

FACILITY - API Number: 05-067- -00 Facility ID: 213993

Facility Name: TIFFANY Number: 1

Qtrqr: NWSE Sec: 26 Twp: 33N Range: 7W Meridian: N

Latitude: 37.072410 Longitude: -107.573880

CORRECTIVE ACTIONS:

1 ☒ CA# 160972

Corrective Action: Per Rule 603.o.(4): Secondary containment will prevent Spills or Releases from primary containment vessels, process vessels, or pipelines from migrating horizontally or vertically prior to clean-up.

Date: 05/12/2022

Response: CA COMPLETED

Date of Completion: 04/22/2022

Operator Comment: The secondary containment has been repaired. The liner around the BGT was repaired in a manner that is intended to prevent Spills or Releases from the primary containment.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: The secondary containment has been repaired. The liner around the BGT was repaired in a manner that is intended to prevent Spills or Releases from the primary containment.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Etta Trujillo

Signed: _____

Title: Regulatory Specialist

Date: 6/10/2022 3:59:30 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403075954	FIR RESOLUTION SUBMITTED
403075961	Berm and liner repaired 1
403075963	Berm and liner repaired 2

Total Attach: 3 Files