

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/10/2022

Submitted Date:

06/13/2022

Document Number:

690203031

FIELD INSPECTION FORMLoc ID 308474 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, Evergreen		cogcc.evergreen@enrllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272610	WELL	PR	10/03/2004	GW	071-08095	RENDEZVOUS 41-27	RI

General Comment:

This is a follow up reclamation inspection.
See attached photos and additional details within this report.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Good Housekeeping:

Type	WEEDS		
Comment:	There are noxious weeds beginning to sprout up at the canyon bottom where culvert drainage was repaired. Noxious weeds need to be controled before seed dispersal.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	In Process			

Comment: The road and culverts have been repaired at the drainage areas. It appears work is still in process for stabilization. BMP's must be implemented in accordance with good engineering practice and must be maintained.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Produced Water

Lined:

Pit ID:

Lat:

Long:

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type:

Liner Condition:

Comment:

Corrective Action

Date:

Fencing:

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation: NO2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690203032	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5777929