

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/08/2022

Submitted Date:

06/14/2022

Document Number:

700704307

**FIELD INSPECTION FORM**

Loc ID 314509	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____
------------------	----------------------------------	---	-------------------

**Operator Information:**

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

**Status Summary:**

☐ THIS IS A FOLLOW UP INSPECTION

☒ FOLLOW UP INSPECTION REQUIRED

☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:			
Contact Name	Phone	Email	Comment
, Chevron	661-437-8040	rpuechner@chevron.com	Decommissioning
, Chevron	970-257-6079	stephaniebittner@chevron.com	Admin/Reg Tech
, Chevron	970-257-6004	andrewolson@chevron.com	Operations Superintendent
, Chevron	970-257-6019	cnoc@chevron.com	ALCR

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228882	WELL	SI	12/01/2021	ERIW	103-05874	WILSON CREEK MORRISON UNIT 20	TA

**General Comment:**

COGCC Inspection Report Summary

On Wednesday 6/8/2022 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at Chevron Wilson creek 20, at Location # 314509 in Rio Blanco county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management.

During this inspection the following possible compliance issues were observed:

1. Random debris.
2. Unmarked dead man.
3. BMP's are failing and sediment migration.
4. No well head signage.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:				
Corrective Action	L		Date:	
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	OTHER			
Comment:	Entrance signage			
Corrective Action:			Date:	
Type	WELLHEAD			
Comment:	No well head signage.			
Corrective Action:	Provide proper signage untill well head is cut off.		Date:	07/26/2022
Emergency Contact Number:				
Comment:	911			
Corrective Action:			Date:	
<b>Good Housekeeping:</b>				
Type	DEBRIS			
Comment:	Random debris			
Corrective Action:	Remove Debris		Date:	06/23/2022
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Equipment:</b>				
Type: Other	# 1		corrective date	
Comment:	Well head			
Corrective Action:			Date:	
Type: Deadman # & Marked	# 4			
Comment:	1 dead man is unmarked			
Corrective Action:	Mark or remove deadman		Date:	07/26/2022
Type: Bradenhead	# 1			
Comment:				
Corrective Action:			Date:	
<b>Venting:</b>				
Yes/No	NO			
Comment:				

Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	228882	Type:	WELL	API Number:	103-05874	Status:	SI	Insp. Status:	TA
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned									
Reminder: _____									
Comment: _____									
Corrective Action: _____									
Date: _____									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Fail					

Comment: 1. BMP's are failing and sediment migration.

Corrective Action: Install or repair required BMPs

Date: 08/02/2022

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700704313	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5779429">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5779429</a>