

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403080087

Date Received:
06/15/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10767

Name of Operator: TWIN BRIDGES RESOURCES LLC

Address: 475 17TH ST., STE 900

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Kelly Rogowski

Phone

7204076509

Email

krogowski@twinbridgesllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 690202968

Inspection Date: 05/31/2022

FIR Submit Date: 06/01/2022

FIR Status: _____

Inspected Operator Information:

Company Name: TWIN BRIDGES RESOURCES LLC

Company Number: 10767

Address: 475 17TH ST., STE 900

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 481116

Location Name: Red Rocks Number: 35-15 County: LAS ANIMAS

Qtrqr: NWNE Sec: 35 Twp: 29S Range: 55W Meridian: 6

Latitude: 37.478380 Longitude: -103.543750

FACILITY - API Number: 05-071- -00 Facility ID: 481333

Facility Name: Red Rocks Number: 35-15

Qtrqr: NWNE Sec: 35 Twp: 29S Range: 55W Meridian: 6

Latitude: 37.478380 Longitude: -103.543750

CORRECTIVE ACTIONS:

1 ☒ CA# 162369

Corrective Action: Comply with 602.c.

Date: 06/08/2022

Response: CA COMPLETED

Date of Completion: 06/08/2022

Operator
Comment:

Wellhead cellar covered to prevent livestock/wildlife entry.

COGCC Decision: Approved

COGCC
Representative:

2 ☒ CA# 162370

Corrective Action: Comply with Rule 606

Date: 06/30/2022

Response: CA COMPLETED

Date of Completion: 06/08/2022

Operator
Comment:

All equipment has been removed from location and is now in compliance with Rule 606.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 ☒ CA# 162371

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 06/08/2022

Response: CA COMPLETED

Date of Completion: 06/08/2022

Operator
Comment:

All wattles properly staked down to protect downgradient runoff from disturbed areas. Silt fence was removed around cuttings pile because cuttings pile was hauled off location. Silt fence is no longer applicable or necessary at location.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

4 ☒ CA# 162372

Corrective Action: Comply with 905.g.
COGCC EPS staff (Jason Kosola) for directives.

Date: 06/02/2022

Response: CA COMPLETED

Date of Completion: 06/01/2022

Operator
Comment:

Contacted Jason on 6/1/2022. Cuttings pile was removed from location. No additional sampling or protection needed for cuttings pile.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Kelly Rogowski

Signed: _____

Title: Land Manager

Date: 6/15/2022 11:28:19 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403080087	FIR RESOLUTION SUBMITTED
403080329	Cellar
403080331	Wattles
403080332	Wattles
403080333	Wellhead
403080334	Location

Total Attach: 6 Files