

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/09/2022

Submitted Date:

06/15/2022

Document Number:

700901148**FIELD INSPECTION FORM**Loc ID 320339 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203490	WELL	PR	12/01/2017	OW	001-09050	BADGER OIL 1	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:	Rule 605.h. Signs and Markers Tanks and Containers.		
Corrective Action:	Corrective Action Date 30 days, See attached photo # 14.	Date:	07/15/2022

Emergency Contact Number:	
Comment:	Adequate
Corrective Action:	
Date:	

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	

Other (Capacity)						
Other (Type)						

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate	
Comment: Rule 603.o.(1) maintain berms around tankk and pits.					
Corrective Action: Corrective Action Date 30 days. See attached photos # 3 through 12.					Date: 07/08/2022

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		39.983788,-104.728208

Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
-----------	----------	--

Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Wells Served By Facilities Above

API Number
001-09050

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 203490 Type: WELL API Number: 001-09050 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: Annual Brhd Completed?

Last Brhd Test Results Initial Surf Csg Pressure: Fluid Type:

End Surf Csg Pressure:

Comment: Appers to be plumbed to surface

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary
 On Thursday June 9, 2022 at approximately 10:30am. I, Inspector Chane Finkenbinder, conducted an on-site inspection.
 Operator: Fritzler Resources INC
 Location / Well name: Badger Oil #1
 API # 001-09050
 Location ID #: 320339
 County: Adams
 While there, I observed a producing well.
 During this inspection the following possible compliance issues were observed:
 Rule 603.o.(1) maintain berms around tank and pits. Corrective Action Date 30 days. See attached photos # 3 through 12.
 Rule 605.h. Signs and Markers Tanks and Containers. Corrective Action Date 30 days, See attached photo # 14.
 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

finkenbc

06/09/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700901149	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5781117