

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403082111

Date Received:
06/16/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87401

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Etta Trujillo

505-324-4154

etrujillo@logosresourcesllc.com

Vanessa Fields

505-787-2218

vfields@logosresourcesllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693904338

Inspection Date: 03/21/2022

FIR Submit Date: 04/04/2022

FIR Status: _____

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC

Company Number: 10679

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87401

LOCATION - Location ID: 306954

Location Name: BONDAD 33-9-N33N9W Number: 31NWSW County: LA PLATA

Qtrqr: NWS Sec: 31 Twp: 33N Range: 9W Meridian: N

Latitude: 37.058290 Longitude: -107.874530

FACILITY - API Number: 05-067- -00 Facility ID: 284286

Facility Name: BONDAD 33-9 Number: 54

Qtrqr: NWS Sec: 31 Twp: 33N Range: 9W Meridian: N

Latitude: 37.058290 Longitude: -107.874530

CORRECTIVE ACTIONS:

1 CA# 160627

Corrective Action: -Open cellar needs cover for wildlife protection by 5/1/2022.

Date: 05/01/2022

Response: CA COMPLETED

Date of Completion: 06/15/2022

Operator
Comment:

The Open cellar has been covered for wildlife protection (please see picture)

COGCC Decision: _____

COGCC
Representative: _____

2 CA# 160628

Corrective Action: -Revegetation needs to be conducted at the well pad entrance and along the pipeline right of way, near the well pad entrance by 5/1/2020.

Date: 05/01/2020

-Spot seeding and erosion control (ie mulching) need to be applied to portions of the southeastern interim reclamation area where it appears that vegetation is killed from potential herbicide overspray. Corrective action date: 5/1/2022.

Response: CA COMPLETED

Date of Completion: 06/15/2022

Operator Comment: Logos operating worked with Harvest midstream and revegetation was conducted at the well pad entrance and along the pipeline right of way, near the well pad entrance.

COGCC Decision: _____

COGCC
Representative: _____

3 CA# 160629

Corrective Action: Stormwater controls (BMPs) and erosion controls (ie mulch) need to be applied in portions of the project area with sparse, bare, and dead vegetation, as well as areas where concentrated stormwater flows off of the well pad and through culvert along access.

Date: 05/01/2020

Response: CA COMPLETED

Date of Completion: 06/15/2022

Operator Comment: Spot seeding and erosion control (ie mulching) was applied to portions of the southeastern interim reclamation area where the vegetation was largely dead.

Stormwater controls (BMPs) and erosion controls were applied to portions of the project area with sparse, bare, and dead vegetation existed, also in areas where concentrated stormwater flows through the culvert along access road.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: The Open cellar has been covered for wildlife protection (please see picture)

Logos operating worked with Harvest midstream and revegetation was conducted at the well pad entrance and along the pipeline right of way, near the well pad entrance.

Spot seeding and erosion control (ie mulching) was applied to portions of the southeastern interim reclamation area where the vegetation was largely dead.

Stormwater controls (BMPs) and erosion controls were applied to portions of the project area with sparse, bare, and dead vegetation existed, also in areas where concentrated stormwater flows through the culvert along access road.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Etta Trujillo

Signed: _____

Title: Regulatory Specialist

Date: 6/16/2022 1:43:32 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403082122	Bare soil seeded and mulched - Culvert inlet
403082128	Bare soil seeded and mulched 1
403082132	Bare soil seeded and mulched 2
403082135	Bare soil seeded and mulched 3
403082137	Cellar Cover
403082139	Culvert Inlet 1
403082142	Culvert Inlet 2

Total Attach: 7 Files