

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403084467

Date Received:
06/20/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1875 LAWRENCE ST STE 1150
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 695106037
Inspection Date: 04/12/2022 FIR Submit Date: 04/12/2022 FIR Status:

Inspected Operator Information:

Company Name: EVERGREEN NATURAL RESOURCES LLC Company Number: 10705
Address: 1875 LAWRENCE ST STE 1150
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 333968

Location Name: Lynn Number: 32-4 Tr County: LAS ANIMAS
Qtrqtr: SWNE Sec: 4 Twp: 33S Range: 67W Meridian: 6
Latitude: 37.202010 Longitude: -104.889420

FACILITY - API Number: 05-071-00 Facility ID: 300358

Facility Name: Lynn Number: 32-4 Tr
Qtrqtr: SWNE Sec: 4 Twp: 33S Range: 67W Meridian: 6
Latitude: 37.202010 Longitude: -104.889420

CORRECTIVE ACTIONS:

1 CA# 160974

Corrective Action: REMOVE UNUSED RISER PER RULE 606. (RISER HAS BEEN DAMMAGED AND THERE IS ALREADY A FUEL SUPPLY FOR THE PUMPJACK, THIS RISER MUST BE REMOVED).

Date: 04/23/2022

Response: CA COMPLETED Date of Completion: 06/15/2022

Operator Comment: Repaired and put riser unuse per Rule 606.

COGCC Decision: _____

COGCC
Representative:

2 CA# 160975

Corrective Action: REMOVE OR REPAIR UNUSED EQUIPMENT. NOTE THIS IS THE SECOND NOTICE FOR THIS CA. IMMEDIATE ACTION IS REQUIRED.

Date: _____

Response: CA COMPLETED

Date of Completion: 06/15/2022

Operator
Comment: Repaired and put riser unuse per Rule 606.

Repaired and put riser unuse per Rule 606.

COGCC Decision: _____

COGCC
Representative:

3 CA# 160976

Corrective Action: Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2). THIS IS THE SECOND NOTICE FOR THIS CORRECTIVE ACTION, IMMEDIATE ACTION IS REQUIRED.

Date: _____

Response: CA COMPLETED

Date of Completion: 06/15/2022

Operator
Comment: Installed appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1),

Installed appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1),

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Please find the attached Photo's

Please find the attached Photo's

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Susan Wolfram

Signed: _____

Title: Sr. Safety Coordinator

Date: 6/20/2022 6:10:05 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403084473	Lynn 32-4
-----------	-----------

Total Attach: 1 Files