

Lynn 32-4





Repaired and put riser unuse per Rule 606.





Installed appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1),