

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403072041

Date Received:

06/08/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10663

Name of Operator: ENDURING RESOURCES LLC

Address: 6300 S SYRACUSE WAY, SUITE 525

City: CENTENNIAL State: CO Zip: 80111

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Hartman, Laura

lhartman@blm.gov

Walter, Kyle

kwalter@enduringresources.com

Huntington, Heather

hhuntington@enduringresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693904458

Inspection Date: 04/29/2022

FIR Submit Date: 05/05/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: 44 CANYON LLC

Company Number: 195

Address: 1400 SMITH STREET #44195

City: HOUSTON State: TX Zip: 77002

LOCATION - Location ID: 385787

Location Name: FEDERAL-N34.5N9W Number: 34SESE County: LA PLATA

Qtrqr: SESE Sec: 34 Twp: 34.5N Range: 9W Meridian: N

Latitude: 37.247066 Longitude: -107.836198

FACILITY - API Number: 05-067- -00 Facility ID: 215909

Facility Name: FEDERAL Number: 34-1/2-34-1

Qtrqr: SESE Sec: 34 Twp: 34.5N Range: 9W Meridian: N

Latitude: 37.247066 Longitude: -107.836198

CORRECTIVE ACTIONS:

1 ☒ CA# 161645

Corrective Action:

-Spot seeding needs to be conducted in areas with sparse desirable vegetation such as the southern and southwestern fill slopes by 10/1/2022.

Date: 10/01/2022

Response: CA COMPLETED

Date of Completion: 06/08/2022

BLM as Lessor has advised that no further surface actions are required by Enduring at this time. Attached for reference is previous BLM correspondence on the location along with an approved FAN dated 8/4/2015.

Operator  
Comment:

COGCC Decision: **Not Approved**

COGCC Representative: Operator needs to be in compliance with COGCC rules. Operator response does not demonstrate adequate response to corrective action.

2 CA# 161646

Corrective Action: -Stormwater controls need to be installed to stabilize erosion within the sproject area by 6/5/2022.

Date: 06/05/2022

Response: CA COMPLETED

Date of Completion: 06/08/2022

Operator Comment: BLM as Lessor has advised that no further surface actions are required by Enduring at this time. Attached for reference is previous BLM correspondence on the location along with an approved FAN dated 8/4/2015.

COGCC Decision: **Not Approved**

COGCC Representative: Operator needs to be in compliance with COGCC rules. Operator response does not demonstrate adequate response to corrective action.

#### OPERATOR COMMENT AND SUBMITTAL

Comment: BLM as Lessor has advised that no further surface actions are required by Enduring at this time. Attached for reference is previous BLM correspondence on the location along with an approved FAN dated 8/4/2015.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Heather Huntington

Signed:

Title: Permitting Tech

Date: 6/8/2022 1:14:59 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403072041	FIR RESOLUTION SUBMITTED
403072050	BLM DOCUMENTATION

Total Attach: 2 Files