

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403084467

Date Received:

06/20/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Distribution, Evergreen

719-846-7898

cogcc.evergreen@enrllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 695106037

Inspection Date: 04/12/2022

FIR Submit Date: 04/12/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: EVERGREEN NATURAL RESOURCES LLC

Company Number: 10705

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 333968

Location Name: Lynn Number: 32-4 Tr County: LAS ANIMAS

Qtrqr: SWNE Sec: 4 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.202010 Longitude: -104.889420

FACILITY - API Number: 05-071- -00 Facility ID: 300358

Facility Name: Lynn Number: 32-4 Tr

Qtrqr: SWNE Sec: 4 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.202010 Longitude: -104.889420

CORRECTIVE ACTIONS:

1 ☒ CA# 160974

Corrective Action: REMOVE UNUSED RISER PER RULE 606. (RISER HAS BEEN DAMMAGED AND THERE IS ALREADY A FUEL SUPPLY FOR THE PUMPJACK, THIS RISER MUST BE REMOVED).

Date: 04/23/2022

Response: CA COMPLETED

Date of Completion: 06/15/2022

Operator Comment: Repaired and put riser unuse per Rule 606.

COGCC Decision: Approved via an AMI

COGCC  
Representative:

2 ☒ CA# 160975

Corrective Action: REMOVE OR REPAIR UNUSED EQUIPMENT. NOTE THIS IS THE SECOND NOTICE FOR THIS CA. IMMEDIATE ACTION IS REQUIRED.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 06/15/2022

Operator  
Comment: Repaired and put riser unuse per Rule 606.

COGCC Decision: Approved via an AMI

COGCC  
Representative:

3 ☒ CA# 160976

Corrective Action: Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2). THIS IS THE SECOND NOTICE FOR THIS CORRECTIVE ACTION, IMMEDIATE ACTION IS REQUIRED.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 06/15/2022

Operator  
Comment: Installed appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1),

COGCC Decision: Approved via an AMI

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Please find the attached Photo's

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Susan Wolfram

Signed: \_\_\_\_\_

Title: Sr. Safety Coordinator

Date: 6/20/2022 6:10:05 PM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403084467	FIR RESOLUTION SUBMITTED
403084473	Lynn 32-4

Total Attach: 2 Files