

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403049356

Date Received:
05/13/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
.		sninspections@ikavenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900701

Inspection Date: 08/21/2019

FIR Submit Date: 08/22/2019

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 306861

Location Name: FEINBERG GAS UNIT C-N35N6W Number: 28NWSW County: LA PLATA

Qtrqtr: NWS Sec: 28 Twp: 35N Range: 6W Meridian: N
W

Latitude: 37.270211 Longitude: -107.538160

FACILITY - API Number: 05-067-00 Facility ID: 270213

Facility Name: FEINBERG C Number: 2

Qtrqtr: NWS Sec: 28 Twp: 35N Range: 6W Meridian: N
W

Latitude: 37.270211 Longitude: -107.538160

CORRECTIVE ACTIONS:

1 CA# 129582

Corrective Action: Seeded areas should be monitored and if not becoming established by fall 2019, then re-seeding will be required again. As mentioned above, reducing mortality from livestock or wildlife will help vegetation establishment. Corrective action is back-dated to document original corrective action date. The corrective action will be satisfied when the cut-slope is stabilized with vegetation.

Date: 11/15/2018

Response: CA COMPLETED Date of Completion: 03/31/2022

Repaired and re-staked waddles on cut slope, reseeded and laid straw over seed, rebuilt throat of rock run out.

Operator
Comment:

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 CA# 129583

Corrective Action: Stormwater erosion needs to be controlled within the project area. BMPs need to be selected, sized, installed, and maintained in accordance with good engineering practices such as those described by CDOT in erosion control manuals. Corrective action is backdated to document original corrective action date.

Date: 11/15/2018

Response: CA COMPLETED

Date of Completion: 03/31/2022

Operator
Comment:

Additional storm water work was performed on 9/24/2019 which included removal of previously installed wattles, Installation of an armored silt trap to reduce velocity as water exits the well pad and armoring the run down for additional reduction of velocity. Berming installed to direct stormwater to the silt trap and prevent additional cutting in the fill slope of the well pad. See attached photos of work completed 9/24/2019.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA Completed. See attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Grace Bryson

Signed: _____

Title: Permitting Specialist I

Date: 5/13/2022 2:13:33 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403049356	FIR RESOLUTION SUBMITTED
403049423	Feinberg C2, CA Completion Photos

Total Attach: 2 Files