

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403062698

Date Received:
05/31/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10663
Name of Operator: ENDURING RESOURCES LLC
Address: 6300 S SYRACUSE WAY, SUITE 525
City: CENTENNIAL State: CO Zip: 80111

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Huntington, Heather		hhuntington@enduringresources.com
Walter, Kyle		kwalter@enduringresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693904504
Inspection Date: 05/13/2022 FIR Submit Date: 05/17/2022 FIR Status:

Inspected Operator Information:

Company Name: ENDURING RESOURCES LLC Company Number: 10663
Address: 6300 S SYRACUSE WAY, SUITE 525
City: CENTENNIAL State: CO Zip: 80111

LOCATION - Location ID: 326208

Location Name: INDIAN CREEK WHEELER- M34N10W Number: 13SENW County: LA PLATA
Qtrqr: SENW Sec: 13 Twp: 34N Range: 10W Meridian: M
Latitude: 37.193352 Longitude: -107.885371

FACILITY - API Number: 05-067- -00 Facility ID: 216044

Facility Name: INDIAN CREEK WHEELER Number: 13-2
Qtrqr: SENW Sec: 13 Twp: 34N Range: 10W Meridian: M
Latitude: 37.193352 Longitude: -107.885371

CORRECTIVE ACTIONS:

1 CA# 161980

Corrective Action: Control weeds. Corrective action date is reduced as weeds are in a flowering condition and need control before seed set. Date: 05/27/2022

Response: CA COMPLETED Date of Completion: 05/27/2022

Operator Comment: Weeds were treated see photos attached

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 CA# 161981

Corrective Action: -Stormwater and erosion controls need to be installed to stabilize erosion on the well pad and access road. Stormwater and erosion controls need to be selected, sized, installed, and maintained according to good engineering practices that will ensure long-term stabilization such as those described by CDOT in their erosion control manuals. Response to 2020 corrective action to address stormwater erosion on the access road remains inadequate. Corrective action date: 10/10/2021.

Date: _____

Response: CA COMPLETED

Date of Completion: 05/27/2022

Operator
Comment:

Storm water control measures installed, see attached photos

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Heather Huntington

Signed: _____

Title: Permitting Tech

Date: 5/31/2022 8:22:14 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403062698	FIR RESOLUTION SUBMITTED
403062703	CA PHOTOS

Total Attach: 2 Files