

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403091240

Date Received:

06/28/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

0 CA Completed  
2 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10112

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Keister, Cindy

(817) 665-5572

ckeister@qrinc.com

Tami Humphrey

thumphrey@qrinc.com

Beard, Alyssa

720-257-2302 303-244-8114

ABeard@foundationenergy.com

regulatory@foundationenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 702800365

Inspection Date: 06/16/2022

FIR Submit Date: 06/27/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: FOUNDATION ENERGY MANAGEMENT LLC

Company Number: 10112

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

LOCATION - Location ID: 333052

Location Name: ARKANSAS POST-67N93W Number: 12SENW County: \_\_\_\_\_

Qtrqr: SENW Sec: 12 Twp: 7N Range: 93W Meridian: 6

Latitude: 40.574870 Longitude: -107.783800

FACILITY - API Number: 05-081- -00 Facility ID: 333052

Facility Name: ARKANSAS POST-67N93W Number: 12SENW

Qtrqr: SENW Sec: 12 Twp: 7N Range: 93W Meridian: 6

Latitude: 40.574870 Longitude: -107.783800

CORRECTIVE ACTIONS:

1 CA# 162935

Corrective Action: Conduct weed management to prevent further establishment and spread of noxious weeds and undesirable plant species on the entire Location; ongoing weed management required until location passes final reclamation.

Date: 07/01/2022

Response: FACTUAL REVIEW REQUEST

Basis for Review: Operator does not own or operate the location

Operator Comment: Foundation sold this well to Quicksilver Resources in 2010, but it has not yet been transferred in COGCC's records.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**2** CA# 162936

Corrective Action: Conduct additional reclamation in accordance with COGCC 1000 series rules. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local soil conservation district. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed. Revegetation activities shall be completed no later than 11/15/2022.

Date: 11/15/2022

Response: FACTUAL REVIEW REQUEST

Basis for Review: Operator does not own or operate the location

Operator Comment: Foundation sold this well to Quicksilver Resources in 2010, but it has not yet been transferred in COGCC's records.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Factual review requested as Foundation is no longer owner/operator of this location. Foundation is currently waiting to hear back from COGCC for resolution of the transfer of operator issue.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Afton Iiams

Signed: \_\_\_\_\_

Title: HSE/Regulatory Technician

Date: 6/28/2022 8:18:28 AM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files