

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403091251

Date Received:
06/28/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

0 CA Completed
2 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Humphrey, Tami</u>	<u>(817) 665-4876 x4876</u>	<u>thumphrey@qrinc.com</u>
<u>Keister, Cindy</u>	<u>(817) 665-5572</u>	<u>ckeister@qrinc.com</u>
<u>Beard, Alyssa</u>		<u>ABeard@foundationenergy.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 702800366
Inspection Date: 06/16/2022 FIR Submit Date: 06/27/2022 FIR Status: _____

Inspected Operator Information:

Company Name: FOUNDATION ENERGY MANAGEMENT LLC Company Number: 10112
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

LOCATION - Location ID: 313334

Location Name: DONALD-67N93W Number: 11NWNE County: _____
Qtrqr: NWNE Sec: 11 Twp: 7N Range: 93W Meridian: 6
Latitude: 40.578020 Longitude: -107.797920

FACILITY - API Number: 05-081-00 Facility ID: 313334

Facility Name: DONALD-67N93W Number: 11NWNE
Qtrqr: NWNE Sec: 11 Twp: 7N Range: 93W Meridian: 6
Latitude: 40.578020 Longitude: -107.797920

CORRECTIVE ACTIONS:

1 CA# 162937

Corrective Action: Conduct weed management to prevent further establishment and spread of noxious weeds and undesirable plant species on the entire Location; ongoing weed management required until location passes final reclamation.

Date: 07/02/2022

Response: FACTUAL REVIEW REQUEST

Basis for Review: Operator does not own or operate the location

Operator Comment: Foundation sold this well to Quicksilver Resources in 2010, but it has not yet been transferred in COGCC's records.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 162938

Corrective Action: Comply with 1004 Rules. Remove all equipment both on and off Location associated with the Location and reclaim areas impacted by removal. Perform final reclamation as applicable on the Location including but not limited to compaction alleviation (cross ripping to a minimum depth of 18 inches) or documentation of previous Location decompaction, berm and stormwater BMP removal and recontouring, and revegetation of the Location. Use a seed mix from the surface owner, or prescribed by the local soil conservation district.

Date: 06/27/2022

Response: FACTUAL REVIEW REQUEST

Basis for Review: Operator does not own or operate the location

Operator Comment: Foundation sold this well to Quicksilver Resources in 2010, but it has not yet been transferred in COGCC's records.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Factual review requested as Foundation is no longer owner/operator of this location. Foundation is currently waiting to hear back from COGCC for resolution of the transfer or operator issue.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Afton Iiams

Signed: _____

Title: HSE/Regulatory Technician

Date: 6/28/2022 8:22:32 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files