

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403091251

Date Received:

06/28/2022

FIR RESOLUTION FORM

Overall Status: FRQ

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

0 CA Completed
2 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10112

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Humphrey, Tami</u>	<u>(817) 665-4876 x4876</u>	<u>thumphrey@grinc.com</u>
<u>Keister, Cindy</u>	<u>(817) 665-5572</u>	<u>ckeister@grinc.com</u>
<u>Beard, Alyssa</u>		<u>ABeard@foundationenergy.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 702800366

Inspection Date: 06/16/2022

FIR Submit Date: 06/27/2022

FIR Status: _____

Inspected Operator Information:

Company Name: FOUNDATION ENERGY MANAGEMENT LLC

Company Number: 10112

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

LOCATION - Location ID: 313334

Location Name: DONALD-67N93W Number: 11NWNE County: _____

Qtrqr: NWNE Sec: 11 Twp: 7N Range: 93W Meridian: 6

Latitude: 40.578020 Longitude: -107.797920

FACILITY - API Number: 05-081-00 Facility ID: 313334

Facility Name: DONALD-67N93W Number: 11NWNE

Qtrqr: NWNE Sec: 11 Twp: 7N Range: 93W Meridian: 6

Latitude: 40.578020 Longitude: -107.797920

CORRECTIVE ACTIONS:

1 ☒ CA# 162937

Corrective Action: Conduct weed management to prevent further establishment and spread of noxious weeds and undesirable plant species on the entire Location; ongoing weed management required until location passes final reclamation.

Date: 07/02/2022

Response: FACTUAL REVIEW REQUEST

Basis for Review: Operator does not own or operate the location

Operator Comment: Foundation sold this well to Quicksilver Resources in 2010, but it has not yet been transferred in COGCC's records.

COGCC Decision: **Not Approved**

COGCC Representative: Presently, according to COGCC records Foundation Energy Management LLC is the Operator of this Location.
Form 10 Change of Operator (doc #402518194) to change the Operator to Quicksilver Resources Inc is "In Process." Until the change of Operator Form is approved by COGCC, both Operators will receive inspection reports.

COGCC Supervisor: Presently, according to COGCC records Foundation Energy Management LLC is the Operator of this Location.
Form 10 Change of Operator (doc #402518194) to change the Operator to Quicksilver Resources Inc is "In Process." Until the change of Operator Form is approved by COGCC, both Operators will receive inspection reports.

2  CA# 162938

Corrective Action: Comply with 1004 Rules. Remove all equipment both on and off Location associated with the Location and reclaim areas impacted by removal. Perform final reclamation as applicable on the Location including but not limited to compaction alleviation (cross ripping to a minimum depth of 18 inches) or documentation of previous Location decompaction, berm and stormwater BMP removal and recontouring, and revegetation of the Location. Use a seed mix from the surface owner, or prescribed by the local soil conservation district.

Date: 06/27/2022

Response: FACTUAL REVIEW REQUEST

Basis for Review: Operator does not own or operate the location

Operator Comment: Foundation sold this well to Quicksilver Resources in 2010, but it has not yet been transferred in COGCC's records.

COGCC Decision: **Not Approved**

COGCC Representative: Presently, according to COGCC records Foundation Energy Management LLC is the Operator of this Location.
Form 10 Change of Operator (doc #402518194) to change the Operator to Quicksilver Resources Inc is "In Process." Until the change of Operator Form is approved by COGCC, both Operators will receive inspection reports.

COGCC Supervisor: Presently, according to COGCC records Foundation Energy Management LLC is the Operator of this Location.
Form 10 Change of Operator (doc #402518194) to change the Operator to Quicksilver Resources Inc is "In Process." Until the change of Operator Form is approved by COGCC, both Operators will receive inspection reports.

OPERATOR COMMENT AND SUBMITTAL

Comment: Factual review requested as Foundation is no longer owner/operator of this location. Foundation is currently waiting to hear back from COGCC for resolution of the transfer or operator issue.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Afton Iiams

Signed: _____

Title: HSE/Regulatory Technician

Date: 6/28/2022 8:22:32 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403091251	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files

Date Run: 6/28/2022 Doc [#403091251]

Page 2 of 2