

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403071953

Date Received:

06/08/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Bittner, Dawn

stephaniebittner@chevron.com

Olson, Andrew

AndrewOlson@chevron.com

Puechner, Rachel

RPuechner@chevron.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 702800188

Inspection Date: 05/06/2022

FIR Submit Date: 05/11/2022

FIR Status: _____

Inspected Operator Information:

Company Name: CHEVRON USA INC

Company Number: 16700

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

LOCATION - Location ID: 314496

Location Name: WILSON CREEK UNIT-62N94W Number: 2NESE County: _____

Qtrqtr: NESE Sec: 2 Twp: 2N Range: 94W Meridian: 6

Latitude: 40.169692 Longitude: -107.899017

FACILITY - API Number: 05-103- -00 Facility ID: 314496

Facility Name: WILSON CREEK UNIT-62N94W Number: 2NESE

Qtrqtr: NESE Sec: 2 Twp: 2N Range: 94W Meridian: 6

Latitude: 40.169692 Longitude: -107.899017

CORRECTIVE ACTIONS:

1 ☒ CA# 161762

Corrective Action: Install or repair wildlife protection equipment.

Date: 05/16/2022

Response: CA COMPLETED

Date of Completion: 05/19/2022

Chemical tank was removed from Location. Picture is attached

Operator
Comment:

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. Photo appears to show equipment was removed from the Location. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

2 ☒ CA# 161763

Corrective Action: Install or repair required BMPs per Rule 1002.f. Continue to monitor and manage stormwater on the Location. Ongoing stormwater management is required until the site receives a passing final inspection.

Date: 06/10/2022

Response: CA COMPLETED

Date of Completion: 05/19/2022

Operator
Comment:

Wattles were installed on Location per Rule 1002.f. Pictures are attached.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. Photos show sediment control BMPs were installed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions are complete

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dawn Bittner

Signed: _____

Title: Administrative Assistant

Date: 6/8/2022 12:36:29 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403071953	FIR RESOLUTION SUBMITTED
403071961	Picture of CA
403071962	Picture of CA

Total Attach: 3 Files