

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403082417

Date Received:

06/16/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Bittner, Dawn

stephaniebittner@chevron.com

Puechner, Rachel

RPuechner@chevron.com

Olson, Andrew

AndrewOlson@chevron.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 702800190

Inspection Date: 05/06/2022

FIR Submit Date: 05/11/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CHEVRON USA INC

Company Number: 16700

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

LOCATION - Location ID: 314505

Location Name: WILSON CREEK UNIT-63N94W Number: 34NESW County: \_\_\_\_\_

Qtrqtr: NESW Sec: 34 Twp: 3N Range: 94W Meridian: 6

Latitude: 40.185651 Longitude: -107.929231

FACILITY - API Number: 05-103- -00 Facility ID: 314505

Facility Name: WILSON CREEK UNIT-63N94W Number: 34NESW

Qtrqtr: NESW Sec: 34 Twp: 3N Range: 94W Meridian: 6

Latitude: 40.185651 Longitude: -107.929231

CORRECTIVE ACTIONS:

1 ☒ CA# 161764

Corrective Action: Install or repair wildlife protection equipment.

Date: 05/16/2022

Response: CA COMPLETED

Date of Completion: 05/18/2022

Chemical tank and all associated parts were removed from location. See attached pictures.

Operator  
Comment:

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. Photo appears to show equipment was removed from the Location. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

2 ☒ CA# 161765

Corrective Action: Install or repair required BMPs per Rule 1002.f. Continue to monitor and manage stormwater on the Location. Ongoing stormwater management is required until the site receives a passing final inspection.

Date: 06/10/2022

Response: CA COMPLETED

Date of Completion: 06/13/2022

Operator  
Comment:

Waddles were repaired or replaced to control sediment migration. See attached pictures

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. Photos show sediment control BMPs were installed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective Actions have been completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dawn Bittner

Signed: \_\_\_\_\_

Title: Administrative Assistant

Date: 6/16/2022 3:40:28 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403082417	FIR RESOLUTION SUBMITTED
403082446	Inspection Photos

Total Attach: 2 Files