

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403082478

Date Received:

06/20/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Bittner, Dawn

970-257-6079

stephaniebittner@chevron.com

O'Nan, Chester

CNOC@chevron.com

Olson, Andrew

AndrewOlson@chevron.com

Puechner, Rachel

RPuechner@chevron.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 702800194

Inspection Date: 05/06/2022

FIR Submit Date: 05/11/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CHEVRON USA INC

Company Number: 16700

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

LOCATION - Location ID: 314509

Location Name: WILSON CREEK MORRISON UNIT-63N94W Number: 34SWNE County: \_\_\_\_\_

Qtrqtr: SWNE Sec: 34 Twp: 3N Range: 94W Meridian: 6

Latitude: 40.189140 Longitude: -107.921130

FACILITY - API Number: 05-103-00 Facility ID: 314509

Facility Name: WILSON CREEK MORRISON UNIT-63N94W Number: 34SWNE

Qtrqtr: SWNE Sec: 34 Twp: 3N Range: 94W Meridian: 6

Latitude: 40.189140 Longitude: -107.921130

CORRECTIVE ACTIONS:

1 ☒ CA# 161783

Corrective Action: Mark or remove guy line anchor.

Date: 05/25/2022

Response: CA COMPLETED

Date of Completion: 06/14/2022

Operator Comment: Guy line anchor was removed.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. Photo appears to show equipment was removed from the Location. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

2 ☒ CA# 161784

Corrective Action: Install or repair required BMPs per Rule 1002.f. Continue to monitor and manage stormwater on the Location. Ongoing stormwater management is required until the site receives a passing final inspection.

Date: 06/10/2022

Response: CA COMPLETED

Date of Completion: 06/14/2022

Operator Comment: Wattles were repaired and replaced to control sediment migration.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. Photos show sediment control BMPs were installed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

#### OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dawn Bittner

Signed: \_\_\_\_\_

Title: Administrative Assistant

Date: 6/20/2022 1:18:43 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403082478	FIR RESOLUTION SUBMITTED
403084074	Corrective Action Photos

Total Attach: 2 Files