

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403084103

Date Received:

06/20/2022

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Puechner, Rachel</u>		<u>RPuechner@chevron.com</u>
<u>O'Nan, Chester</u>		<u>CNOC@chevron.com</u>
<u>Bittner, Dawn</u>	<u>970-257-6079</u>	<u>stephaniebittner@chevron.com</u>
<u>Fischer, Alex</u>		<u>alex.fischer@state.co.us</u>
<u>Heil, John</u>		<u>john.heil@state.co.us</u>
<u>Olson, Andrew</u>		<u>AndrewOlson@chevron.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 702800265

Inspection Date: 05/25/2022

FIR Submit Date: 06/02/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CHEVRON USA INC

Company Number: 16700

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

LOCATION - Location ID: 314277

Location Name: WILSON CREEK UNIT-63N94W Number: 34NWNW County: \_\_\_\_\_

Qtrqtr: NWN Sec: 34 Twp: 3N Range: 94W Meridian: 6  
W

Latitude: 40.191829 Longitude: -107.933174

FACILITY - API Number: 05-103-00 Facility ID: 314277

Facility Name: WILSON CREEK UNIT-63N94W Number: 34NWNW

Qtrqtr: NWN Sec: 34 Twp: 3N Range: 94W Meridian: 6  
W

Latitude: 40.191829 Longitude: -107.933174

CORRECTIVE ACTIONS:

1  CA# 162392

Corrective Action: Comply with Rule 913.b.(5).B.i.

Date: 05/15/2022

Response: CA COMPLETED

Date of Completion: 05/17/2022

Operator Comment: Panels were installed on 5/17/2022, but were partially down at the time of inspection due to excavation in progress. Panels were reinstalled when excavation was complete and are currently in place.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. Photos show fence panels were installed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

2  CA# 162393

Corrective Action: Corrective Action #1: Comply with Rule 913.b.(5).B.i-v. CA Date: 5/15/2022  
Corrective Action #2: Install or repair required BMPs per Rule 1002.f. CA Date: 6/9/2022

Date: 05/15/2022

Response: CA COMPLETED

Date of Completion: 06/13/2022

Operator Comment: Wattles were installed to control sediment migrations and soil pile was removed.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. Photos show sediment control BMPs were installed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

**OPERATOR COMMENT AND SUBMITTAL**

Comment: All corrective actions have been completed

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dawn Bittner Signed: \_\_\_\_\_

Title: Administrative Assistant Date: 6/20/2022 1:36:36 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
403084103	FIR RESOLUTION SUBMITTED
403084109	Corrective Action Photos

Total Attach: 2 Files