

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/30/2022

Submitted Date:

06/30/2022

Document Number:

695106534

FIELD INSPECTION FORM
 Loc ID 324505 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 66561

Name of Operator: OXY USA INC

Address: PO BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|---------------------------|-------------------------|---------------------|
| Giussani, Albert | 806-894-0200/806-638-1296 | albert_giussani@oxy.com | Engineering Advisor |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------------|-------------|
| 211864 | WELL | SI | 08/01/2020 | GW | 055-06102 | SHEEP MOUNTAIN UNIT 12-2-E | SI |

General Comment:

THIS IS A FACILITY AND SURFACE EQUIPMENT INSPECTION. ANY CORRECTIVE ACTIONS FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE AND ACTION IS REQUIRED.

LocationOverall Good: ☒

| | | | |
|----------------------|--|-------|------------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | WELL SIGN DOES NOT HAVE 911 LISTED AS AN EMERGENCY CONTACT. | | |
| Corrective Action: | IF 911 SERVICES THIS AREA POST 911 AS AN EMERGENCY CONTACT ON THE WELL SIGN. | Date: | 07/30/2022 |
| Type | WELLHEAD | | |
| Comment: | THE API # IS NOT POSTED ON THE WELL SIGN, THE NEW RULES REQUIRE THE API NUMBER TO BE POSTED. IF THE SIGN HAS TO BE REPLACED OR REPAIRED IN THE FUTURE POST THE API # ON WELL SIGN. | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | | |
|--------------------|---------------|--|-------|-----------------|
| Equipment: | | | | corrective date |
| Type: Bradenhead | # 1 | | | |
| Comment: | IS ACCESSABLE | | | |
| Corrective Action: | | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected FacilitiesFacility ID: 211864 Type: WELL API Number: 055-06102 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: WELL IS BEING REPORTED TO THE COGCC AS SHUT IN STATUS, THIS IS NOT CORRECT, THERE IS NO PRODUCTION LINES PLUMBED TO THE WELL THIS MAKES THIS WELL TEMPORARILY ABANDONED.

Corrective Action: PROPERLY REPORT WELL AT TEMPORARILY ABANDON AND FOLLOW THE RULES OF A TEMPORARILY ABANDON WELL. Date: 07/30/2022

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: _____ Lined: YES Pit ID: _____ Lat: 37.648050 Long: -104.180500Reference Point: SE Other: _____ Length: 70 Width: 40**Lining:**

Liner Type:

Liner Condition:

Comment:

Corrective Action

Date:

Fencing:

Fencing Type:

Fencing Condition: Adequate

Comment:

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment: NONE

Corrective Action

Date:

Anchor Trench Present: YESOil Accumulation: NO2+ feet Freeboard: NOComment: THERE IS NO FREEBOARD MARKER INSTALLED IN PIT.

Corrective Action

Date: 07/30/2022**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------|---|
| 695106540 | INSP. PHOTOS | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5793781 |