

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403075227

Date Received:
06/10/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 49100

Name of Operator: KOCH EXPLORATION COMPANY LLC

Address: 950 17TH STREET #1900

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Jordan Radin

720-201-4941

radinj@kochind.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696203685

Inspection Date: 05/10/2022

FIR Submit Date: 05/12/2022

FIR Status: _____

Inspected Operator Information:

Company Name: KOCH EXPLORATION COMPANY LLC

Company Number: 49100

Address: 950 17TH STREET #1900

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 391071

Location Name: HORSESHOE CANYON-69S97W Number: 33SENE County: _____

Qtrqtr: SENE Sec: 33 Twp: 9S Range: 97W Meridian: 6

Latitude: 39.233421 Longitude: -108.216287

FACILITY - API Number: 05-077-00 Facility ID: 391071

Facility Name: HORSESHOE CANYON-69S97W Number: 33SENE

Qtrqtr: SENE Sec: 33 Twp: 9S Range: 97W Meridian: 6

Latitude: 39.233421 Longitude: -108.216287

CORRECTIVE ACTIONS:

1 ☒ CA# 161847

Corrective Action:

Date: 05/31/2022

Comply with 1004 Rules: Conduct reclamation to ensure Location progresses towards 1004 final reclamation standards; establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels.

Conduct weed management to prevent further establishment and spread of Undesirable and Noxious Weed Plant Species; ongoing weed management required until location passes final reclamation.

Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed.

Response: CA COMPLETED

Date of Completion: 06/08/2022

Operator Comment: Reseeding and soil amendments were completed on June 8, 2022. Emergent weeds will continue to be treated as needed.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

2 ☒ CA# 161848

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C. Continue to monitor and manage stormwater on the Location; ensure stormwater sediment and erosion control BMPs are implemented in accordance with good engineering practices, and maintained in proper functioning condition. Ongoing stormwater management is required until site receives a passing final inspection.

Date: 03/07/2022

Response: CA COMPLETED

Date of Completion: 06/08/2022

Operator Comment: Erosion control measures were repaired/replaced on June 8, 2022. Site will be inspected monthly and BMPs maintained as needed.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment: none

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Radin

Signed: _____

Title: Compliance Manager

Date: 6/10/2022 10:03:58 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403075227	FIR RESOLUTION SUBMITTED
-----------	--------------------------

403075262	Photo of site after reseeded
-----------	------------------------------

Total Attach: 2 Files