

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/07/2022

Submitted Date:

07/07/2022

Document Number:

693507516

FIELD INSPECTION FORM

 Loc ID 318749 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 46290
 Name of Operator: KP KAUFFMAN COMPANY INC
 Address: 1700 LINCOLN ST STE 4550
 City: DENVER State: CO Zip: 80203
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 10 Number of Comments
5 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.
,		dnr_cogccenforcement@state.co.us	
,	303-825-4822	cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242099	WELL	SI	11/01/2021	GW	123-09890	UPRR 43 PAN AM I 30	SI

General Comment:

Location			
Lease Road:			
Type	Access		
comment:	No visible road		
Corrective ActionL		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign not legible		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	08/07/2022
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Mechanical issue: Well head has small leak around tubing.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.	Date:	07/08/2022
Type	UNUSED EQUIPMENT		
Comment:	Cement pumping base		
Corrective Action:	Comply with rule 606	Date:	05/05/2022
Type	UNUSED EQUIPMENT		
Comment:	Unused electric line cut on locaiton		
Corrective Action:	Comply with rule 606	Date:	05/05/2022
Type	WEEDS		
Comment:	Weeds on location and around well head.		
Corrective Action:	Comply with rule 606	Date:	08/07/2022
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type			
Comment:			
Corrective Action:		Date:	
Venting:			

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 242099 Type: WELL API Number: 123-09890 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Date of Last Brhd Test: 10/28/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: -- Fluid Type: _____

End Surf Csg Pressure: --

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday June 7 2022 at approximately 11:04AM, I, Inspector Randy Silver, Conducted an on-sitere- inspection per document # 693506177. Location: UPRR 43 Pan AM I30 Operator: KP Kauffman API#:123-09890 County: Weld While there, I observed shut in well site. During this inspection the following possible compliance issues were observed: Unused electric lines: Rule 606 Corrective action date of 2-5-22 see photo 3 Unused equipment: Rule 606 Corrective action date of 2-5-22 See photos 2,4 Mechanical issue: Rule 608 e Corrective action date of 7-8-22 see video Weeds: Rule 606 Corrective action date of 8-7-22 See photos 2,4 Sign: Rule 605 g Corrective action date of 8-7-22 See photo 2 I called Mani Silva KPK supervisor at approx... 11:22AM and informed him of well head leaking around tubing. He stated he would send someone out to repair. This is a reinspection at time of inspection cement base and electric wiring has not been addressed. Weather conditions: Dry A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	07/07/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693507517	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5797397
693507518	video	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5797398