

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/16/2022

Submitted Date:

07/07/2022

Document Number:

699700317

**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
Heil, John 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
,		COGCC.inspections@caerus oilandgas.com	All Inspections
Arauza, Steven		steven.arauza@state.co.us	

**General Comment:**

On June 16, 2022, COGCC Environmental Staff (John Heil) conducted an environmental field inspection of CAERUS PICEANCE LLC (Caerus operator #10456) H29OU Valve Can Release Spill/Release ID 482381.

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_

Estimated Spill Volume: \_\_\_\_\_

Comment: See Spill/Release ID 482381 for more information. 6/16/2022 COGCC staff conducted a visual inspection of the spill/release area as well as the arroyo located north of the spill/release area. COGCC staff observed potential surface impacts and areas near the spill/release where fluids apparently traveled through preferential flow paths in the subsurface. Potential salt staining and impacts were observed in the arroyo located northwest of the spill/release area. COGCC staff documented potential staining and impacts within the arroyo extending approximately 1,170 feet north of the spill/release area. See Photo Log for details.

Corrective Action: Operator shall comply with Rule 913.b.(2) and conduct sampling and analysis of soil and Groundwater (if encountered or a pathway to groundwater is determined) pursuant to Rule 915 to determine the horizontal and vertical extent of any contamination in excess of the cleanup concentrations in Table 915-1 or in WQCC Regulation 41 numeric and narrative Groundwater quality standards and classifications, as incorporated by reference in Rule 901.b.

Date: \_\_\_\_\_

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699700318	20220616 Photo Log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5797589">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5797589</a>