

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/06/2022

Submitted Date:

07/08/2022

Document Number:

690203119

FIELD INSPECTION FORM

 Loc ID 475565 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 34105
 Name of Operator: GILBERT-STEWART OPERATING LLC
 Address: 1801 BROADWAY STE 200
 City: DENVER State: CO Zip: 80202
Findings:

- 3 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
GILBERT KENT L		kgoil@msn.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
475565	LOCATION	AC			-	YELTSIN-615S45W 1SWSE	RI

General Comment:

This is a location inspection.
See attached photos and additional details within this report.

Location

Overall Good:

Signs/Marker:

	Type BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	_____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	There is unused equipment being stored on location that needs to be removed. Pumpjack tanks, ect.		
Corrective Action:	Comply with Rule 606	Date:	08/08/2022

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: _____

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
	0				
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient		
Comment:	The berms around the tanks are inadequate with animal borroughs.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 912.d.(1).			Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690203120	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5798284