

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403100537

Date Received:

07/11/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133  
Name of Operator: HILCORP ENERGY COMPANY  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
Labowskie, Steve		steve.labowskie@state.co.us
_General		FarmingtonRegulatoryTechs@hilcorp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 702500162  
Inspection Date: 07/01/2022 FIR Submit Date: 07/05/2022 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 326530

Location Name: HUBER-CROOK-N35N8W Number: 26SWNE County: LA PLATA  
Qtrqtr: SWNE Sec: 26 Twp: 35N Range: 8W Meridian: N  
Latitude: 37.276930 Longitude: -107.710260

FACILITY - API Number: 05-067-00 Facility ID: 89148

Facility Name: HUBER-CROOK Number: 4-26  
Qtrqtr: SWNE Sec: 26 Twp: 35N Range: 8W Meridian: N  
Latitude: 37.276930 Longitude: -107.710260

CORRECTIVE ACTIONS:

1 CA# 163062

Corrective Action: Use or remove equipment per rule 606. Date: 07/19/2022

Response: CA COMPLETED Date of Completion: 07/08/2022

Operator Comment: Unused equipment and trash around the pump jack and location was removed. See attached photos.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

2 CA# 163063

Corrective Action: Remove trash per rule 606.

Date: 07/13/2022

Response: CA COMPLETED

Date of Completion: 07/08/2022

Operator Comment: Unused equipment and trash around the pump jack and location was removed. See attached photos.

COGCC Decision:

COGCC  
Representative:

3 CA# 163064

Corrective Action: Remove oily residue on floor, remove impacted material and dispose of in approved manner per rule 906 and 1002.f.

Date: 07/19/2022

Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Response: CA COMPLETED

Date of Completion: 07/08/2022

Operator Comment: All residue in the meter house floor and impacted soil was removed and dispose of. See attached photos.

COGCC Decision:

COGCC  
Representative:

4 CA# 163065

Corrective Action: Install proper guy line markers per Rule 1003.a

Date: 07/19/2022

Response: CA COMPLETED

Date of Completion: 07/08/2022

Operator Comment: . Installed rig anchor marked and hooked up the muffler. See attached photos.

COGCC Decision:

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed:

Title: OperationsRegulatory Tech

Date: 7/11/2022 6:11:44 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
403100539	Huber-Crook 4-26_Resolved Photos

Total Attach: 1 Files