

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/06/2022

Submitted Date:

07/07/2022

Document Number:

702500185**FIELD INSPECTION FORM**Loc ID 325648 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96735Name of Operator: WILLIFORD RESOURCES, L.L.C.Address: 6506 S LEWIS AVE STE 102City: TULSA State: OK Zip: 74136**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Williford, Hearne		hwilli@swbell.net	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Stevens, Glenn	(970) 749-0192	glennstevens@centurylink.net	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215165	WELL	PR	06/01/2017	GW	067-06770	SPRING HOLLOW MAC 3	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Phone number: 918-712-8828
Emergency contact: 911

Corrective Action:

Date:

Good Housekeeping:

Type	OTHER		
Comment:	<p>Oily residue at wellhead will begin to impact surface material (IMG 03).</p> <p>Lube oil at prime mover generator is impacting surface material (IMG 04).</p>		
Corrective Action:	Remove impacted material and dispose of in approved manner per rule 906 and 1002.f.	Date:	07/21/2022
Type	UNUSED EQUIPMENT		
Comment:	<p>Unused rod at prime mover (IMG 05).</p> <p>Unused empty drum at pump jack (IMG 06)</p> <p>2 2" black poly lines stubbed up on east edge of location (IMG 08) are unused equipment or out of use flow line.</p>		
Corrective Action:	<p>Use or remove unused equipment per rule 606.</p> <p>If 2" poly lines are flow lines apply Out of Service Locked and Tagged on unused flow line per rule 1101.(3)</p>	Date:	07/14/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Prime Mover	# 1		
Comment:	Gas powered		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead is accessible.		
Corrective Action:		Date:	
Type: Flow Line	# 2		
Comment:	<p>In use: 2" line from wellhead to off location.</p> <p>Not in use: 1" flow line on west edge of location is not locked out/tagged out.</p>		
Corrective Action:	Apply Out of Service Locked and Tagged on unused flow line per rule 1101.(3)	Date:	07/23/2022
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			

Corrective Action:		Date:	
<u>Venting:</u>			
Yes/No			
Comment:			
Corrective Action:		Date:	
<u>Flaring:</u>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID: 215165	Type: WELL	API Number: 067-06770	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
Compaction	Pass					
				Material Handling And Spill Prevention	Pass	

Comment: No observed impact of storm water. Storm water controls seem sufficient at time of report.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403099388	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5797758
702500186	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5797753