

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/06/2022

Submitted Date:

07/08/2022

Document Number:

690203119**FIELD INSPECTION FORM**Loc ID 475565 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 34105

Name of Operator: GILBERT-STEWART OPERATING LLC

Address: 1801 BROADWAY STE 200

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

3 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
GILBERT KENT L		kgoil@msn.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
475565	LOCATION	AC			-	YELTSIN-615S45W 1SWSE	RI

General Comment:

This is a location inspection.
See attached photos and additional details within this report.

LocationOverall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	There is unused equipment being stored on location that needs to be removed. Pumpjack tanks, ect.		
Corrective Action:	Comply with Rule 606	Date:	08/08/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
	0				
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient		
Comment:	The berms around the tanks are inadequate with animal borroughs.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 912.d.(1).			Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403099951	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5798285
690203120	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5798284