


Today's Date:	7/19/2022					
Well Name:	SCHUYLER 34-09-30 2	Location:	Sec: 30	Twn: 034N	Rng: 009W	UL: J
API Number:	05.067.08111	Footage:	1385' FSL & 2085' FEL			
Operator:	Hilcorp Energy Company	Area/Run/MSO:	01	0101	Bob Percell	
Meter #:	06633062		Pipeline:	HEC		
INC Number:	702500244	Agency:	COGCC	Inspector:	Alex Klink	
Type of INC:	Written	Photos Required:	Yes	Due Date:	7/19/2022	
Issue of Concern:	Comment: Fitting in compressor house is releasing produced water. Released produced water is contained within compressor house, but requires immediate attention to prevent produced water from impacting surface material. Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.					
	Comment: Lube oil at both wellheads has impacted material (IMG 03 and IMG 04). Corrective Action: Remove impacted material and dispose of in approved manner per rule 906 and 1002.f.					
	Comment: Produced water tank sign is deteriorated and not legible (IMG 05). Corrective Action: Install sign to comply with Rule 605.h.					



Securely tightened all leaking production equipment





Removed all impacted material around the well head and properly dispose of it



