

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/19/2022

Submitted Date:

07/20/2022

Document Number:

702800461**FIELD INSPECTION FORM**Loc ID 424711 Inspector Name: O'Malley, Anna On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10396Name of Operator: SWN PRODUCTION COMPANY LLCAddress: P.O. BOX 12359City: SPRING State: TX Zip: 77391-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Stepp, Sarah		wccassistant@gmail.com	<a href="#">All Inspections</a>
Pate, James		jsconcrete@yahoo.com	<a href="#">All Inspections</a>
, SWN		swnsandwash@swn.com	<a href="#">All Inspections</a>
Neidel, Kris		kris.neidel@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424711	LOCATION	AC			-	Dawson Creek 1-25	RI

**General Comment:**

On 07/19/2022, Reclamation Specialist O'Malley conducted an interim reclamation and stormwater inspection at Beeman Oil & Gas Inc's Dawson Creek /1-25 Location #424711 in Routt County, Colorado.

The following compliance issues were observed during this inspection:

- Noxious Weeds
- Storage of supplies/unnecessary equipment
- Location overgrown with vegetation
- Stained soils beneath production equipment
- Wildlife protection BMPs missing/insufficient
- Interim reclamation not performed

Refer to the "Location," "Reclamation," and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Form 09 (S) #403026381 to transfer Operatorship from SWN Production Company LLC #10396 to Beeman Oil & Gas Inc #7125 is "In Process". COGCC records show the Operator for this Location as SWN Production Company LLC. Until COGCC records show Beeman Oil & Gas Inc as the Operator, both Operators are included in inspection reports.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	It was observed in this inspection that CO List B Noxious Weeds are present throughout the Location, including on the working pad area, in stormwater ditches and Location perimeter berms. Species include Canada and bull thistle, houndstongue and whitetop.		
Corrective Action:	Conduct weed management to prevent further establishment and spread of Noxious Weeds; ongoing weed management required until location passes final reclamation.	Date:	07/25/2022
Type	STORAGE OF SUPL		
Comment:	Unused equipment including 2 tank stands, and 1 secondary containment tank were observed stored at the well area.		
Corrective Action:	Comply with Rule 606.	Date:	08/04/2022
Type	WEEDS		
Comment:	It was observed in this inspection that the Location, including the access road and around production equipment is overgrown with vegetation.		
Corrective Action:	Comply with Rule 606.	Date:	07/27/2022

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
Other				
Comment:	Impacted soils observed around the wellhead and at the production equipment at the north of the Location. The containment device at the spill at the north of the Location was observed to be insufficient.			
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition. Remove and properly dispose of impacted material as E&P waste. Properly dispose of oily waste in accordance with 905.e.			Date: 08/04/2022

In Containment: No

Comment:

☒ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Other	#		
Comment:	It was observed in this inspection that wildlife protection devices to prevent wildlife, including but not limited to birds and bats from entering the secondary containment stock tank adjacent to the wellhead are missing or insufficient.		
Corrective Action:	Install or repair wildlife protection equipment.		Date: 07/25/2022

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
------	--	--

Comment:			
Corrective Action:		Date:	



**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? Fail Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? Fail

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Fail

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? Fail

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced Fail Recontoured Fail 80% Revegetation Fail

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? F

Comment

Refer to the "Location" section of this inspection report for weed control corrective action.

Per form 2A, document #400170973, approximate size of disturbance during construction: 3.85 acres. Size of Location after interim reclamation: 1.39 acres. COGCC records show 1/20/2013 as date of first production for the well (107-06242). Pursuant to Rule 1003.b, interim reclamation was required to be completed by 7/20/2013.

It was observed in this inspection that areas not reasonably needed for production at the northeast, east and southeast of the Location have not been reclaimed. Inspector is unable to find evidence that interim reclamation was performed. Corrective action date of 11/15/2022 is given to allow for fall seeding.

Corrective Action

Conduct interim reclamation on the Location per 1003 Rules including, but not limited to: gravel removal, compaction alleviation (cross ripping to a minimum depth of 18 inches), recontouring/regrading, replacement of topsoil, and revegetation activities; use a seed mixture provided by the surface owner, or a mixture prescribed by the local soil conservation district. Implement control measures to stabilize the seeded soil per Rule 1002.f.(2)C.

Date 11/15/2022Overall Interim Reclamation Fail**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RANGELAND

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_

Well Release on Active Location ☐Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [At the time of this inspection no stormwater issues were observed. Stormwater control measures are in proper functioning condition. Slopes are stabilized by perennial vegetation.](#)

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702800462	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5808867">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5808867</a>