


Colorado Oil and Gas Conservation Commission

Mustang V41-27-28XRLNB Issue Report



Created on July 22, 2022

Captured on July 21, 2022



Type	Count
Observation	12

No.	Type	Severity	Created	Status	Cost of Repair
5	 Observation	—	July 22, 2022	Open	—
6	 Observation	—	July 22, 2022	Open	—
8	 Observation	—	July 22, 2022	Open	—
9	 Observation	—	July 22, 2022	Open	—
10	 Observation	—	July 22, 2022	Open	—
11	 Observation	—	July 22, 2022	Open	—
12	 Observation	—	July 22, 2022	Open	—
13	 Observation	—	July 22, 2022	Open	—
14	 Observation	—	July 22, 2022	Open	—
15	 Observation	—	July 22, 2022	Open	—
16	 Observation	—	July 22, 2022	Open	—
17	 Observation	—	July 22, 2022	Open	—

Total: \$0.00

5 - Observation

Open

Jul 21, 2022 at 11:27am



Details

Summary: Unused equipment in multiple spots needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 5/6/22

Created: Jul 22, 2022, 9:22am by Adam Burns

Cost of Repair: —

Coordinates: 40.28631, -104.41380

6 - Observation

Open

Jul 21, 2022 at 11:27am



Details

Summary: Trash in multiple spots needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 5/6/22

Created: Jul 22, 2022, 9:22am by Adam Burns


Cost of Repair: —

Coordinates: 40.28614, -104.41399

8 - Observation

Open

Jul 21, 2022 at 11:27am



Details

Summary: Unused equipment in multiple spots needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 5/6/22

Created: Jul 22, 2022, 9:24am by Adam Burns

Cost of Repair: —

Coordinates: 40.28579, -104.41399

9 - Observation

Open

Jul 21, 2022 at 11:27am



Details

Summary: Repair/ Install metal berms around production tanks. Repair or install berms or other secondary containment devices per Rule 912.d.(1). With a corrective action date of 5/13/22

Created: Jul 22, 2022, 9:26am by Adam Burns


Cost of Repair: —

Coordinates: 40.28598, -104.41419

10 - Observation

Open

Jul 21, 2022 at 11:27am



Details

Summary: Trash in multiple spots needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 5/6/22

Created: Jul 22, 2022, 9:27am by Adam Burns

Cost of Repair: —

Coordinates: 40.28588, -104.41439

11 - Observation

Open

Jul 21, 2022 at 11:27am



Details

Summary: Unused equipment in multiple spots needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 5/6/22

Created: Jul 22, 2022, 9:30am by Adam Burns


Cost of Repair: —

Coordinates: 40.28588, -104.41439

12 - Observation

Open

Jul 21, 2022 at 11:27am



Details

Summary: Trash in multiple spots needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 5/6/22

Created: Jul 22, 2022, 9:31am by Adam Burns

Cost of Repair: —

Coordinates: 40.28588, -104.41439


Open

Coordinates: 40.28588, -104.41439

14 - Observation

Open

Jul 21, 2022 at 11:27am



Details

Summary: **Unused equipment in multiple spots needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 5/6/22**

Created: **Jul 22, 2022, 9:32am by Adam Burns**

Cost of Repair: **—**

Coordinates: **40.28588, -104.41439**

15 - Observation

Open

Jul 21, 2022 at 11:27am



Details

Summary: Unused equipment in multiple spots needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 5/6/22

Created: Jul 22, 2022, 9:32am by Adam Burns

Cost of Repair: —

Coordinates: 40.28588, -104.41439

16 - Observation

Open

Jul 21, 2022 at 11:27am



Details

Summary: **Unused production tanks need to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 5/27/22**

Created: **Jul 22, 2022, 9:33am by Adam Burns**

Cost of Repair: **—**

Coordinates: **40.28571, -104.41439**

17 - Observation

Open

Jul 21, 2022 at 11:27am



Details

Summary: Unused equipment in multiple spots needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 5/6/22

Created: Jul 22, 2022, 9:42am by Adam Burns

Cost of Repair: —

Coordinates: 40.28580, -104.41439