

FORM
INSPRev
X/20

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/15/2022

Submitted Date:

07/18/2022

Document Number:

690203159**FIELD INSPECTION FORM**

Loc ID 481718 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10267
Name of Operator: VECTA OIL & GAS LTD
Address: 575 UNION BLVD #208
City: LAKEWOOD State: CO Zip: 80228

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Goolsby, Matt		mdgoolsby@comcast.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
482139	WELL	AP	05/10/2022		071-09921	Sammons 315310C	CI

General Comment:

[This is a construction inspection.](#)
[See attached photos and additional details within this report.](#)

Location Construction

Location ID: 482139 CDP: _____

Comment: There was no topsoil salvaged at the time of inspection. There was some disturbance for the setting of the conductor. Topsoil will need to be salvaged for any excavation and disturbance of the soils per Rule 1002.b.

Corrective Action: _____ **Date:** _____

Form 2A COAs:

Comment: _____

Corrective Action: _____ **Date:** _____

Wildlife BMPs:

Comment: The open top cellar needs to be covered to prevent animal entry.

Corrective Action: _____ **Date:** _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
	No		

Comments: Erosion BMPs: _____

Other BMPs: _____

Corrective Action: _____ **Date:** _____

Comment: There were no stormwater controls installed at the location. Stormwater controls will need to be installed prior to construction.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C **Date:** _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403108017	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5805550
690203160	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5805549