

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403134724

Date Received:
08/12/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Trujillo, Aaron

aaron.trujillo@state.co.us

Arthur, Denise

denise.arthur@state.co.us

General

sjninspections@ikavenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903865

Inspection Date: 11/08/2021

FIR Submit Date: 11/16/2021

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 312051

Location Name: BONDAD 33-9-N33N9W Number: 2SESW County: LA PLATA

Qtrqr: SESW Sec: 2 Twp: 33N Range: 9W Meridian: N

Latitude: 37.129012 Longitude: -107.799810

FACILITY - API Number: 05-067-00 Facility ID: 263927

Facility Name: BARNES A Number: 2

Qtrqr: SESW Sec: 2 Twp: 33N Range: 9W Meridian: N

Latitude: 37.129012 Longitude: -107.799810

CORRECTIVE ACTIONS:

1 CA# 157898

Corrective Action: -Corrective action to submit a shut-in plan per rule 421.b. is not addressed. Per the rule, the operator needs to submit their shut-in plan when requested. The corrective action is back-dated to original corrective action date (8/2/2021) to document duration of non-compliance for enforcement purposes.

Date: 08/02/2021

Response: CA COMPLETED

Date of Completion: 08/10/2022

See attached shut-in plan for wells in designated floodplain also submitted with NOAV 403104776 response.

Operator Comment:			
COGCC Decision:			
COGCC Representative:			
2	CA# 157899		
Corrective Action:	Submit and implement a stormwater control plan. As described in the 7/29/2021 corrective action, the plan needs to demonstrate that stormwater flows will be properly diverted and that the location will be protected from degradation. The plan needs to describe how all inlets and outlets will be properly designed and constructed to ensure stabilization using good engineering practices. To demonstrate that stormwater controls will be implemented per good engineering practices, the stormwater plan needs to be stamped by a Colorado Professional Engineer in good standing. Corrective action is back-dated to initial inspection date (7/29/2021) to document duration of non-compliance for enforcement purposes.		Date: <u>07/29/2021</u>
Response:	<u>CA COMPLETED</u>		Date of Completion: <u>08/10/2022</u>
Operator Comment:	See attached stamped Interim Stormwater Management Plan for Well Location 312051 and implementation photo log also submitted with NOAV 403104776 response.		
COGCC Decision:			
COGCC Representative:			

<u>OPERATOR COMMENT AND SUBMITTAL</u>	
Comment:	Both attachments were also submitted with the NOAV 403104776 response.
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name: <u>Katherine Feir</u>	Signed: _____
Title: <u>Compliance Coordinator</u>	Date: <u>8/12/2022 2:59:28 PM</u>

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403134902	Barnes A2 Interim SWMP and Implementation Photo Log
403134904	SIMCOE Shut in Plan for Wells in Designated Floodplain

Total Attach: 2 Files