

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403138102

Date Received:

08/16/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 8 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Romana Cowden

720-951-5895

COGCC.inspections@caerusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696203781

Inspection Date: 06/22/2022

FIR Submit Date: 06/24/2022

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 467272

Location Name: ELU J14 Number: FED-496 County: _____
PAD

Qtrqtr: NESW Sec: 14 Twp: 4S Range: 96W Meridian: 6

Latitude: 39.700947 Longitude: -108.137218

FACILITY - API Number: 05-103- -00 Facility ID: 467272

Facility Name: ELU J14 Number: FED-496
PAD

Qtrqtr: NESW Sec: 14 Twp: 4S Range: 96W Meridian: 6

Latitude: 39.700947 Longitude: -108.137218

CORRECTIVE ACTIONS:

7 ☒ CA# 162911

Corrective Action: Comply with Rule 1002.b and 1002.c

Date: 06/18/2022

Response: CA COMPLETED

Date of Completion: 08/16/2022

Operator Comment: Extended and repaired armored inlet into sediment trap.

COGCC Decision: **Not Approved**

COGCC Representative: Unable to approve resolution; corrective action requiring compliance with Rule 1002.b and 1002.c is related to protection of soils. Operator comments appear to be addressing a corrective action regarding maintenance of an inlet to a sediment trap.

8  CA# 162912

Corrective Action: Install or repair required BMPs per Rule 1002.f. Ensure control measures are adequate for the site's conditions, implemented in accordance with good engineering practices, and maintained in proper functioning condition.

Date: 05/25/2022

Response: CA COMPLETED

Date of Completion: 07/11/2022

Operator Comment: Repaired and extended armoring of inlet into sediment trap. Also removed weeds and stained soil.

COGCC Decision: **Not Approved**

COGCC Representative: Unable to approve resolution; corrective action is related to protection of soils, stormwater management, in addition to inlet. Operator comments does not provide details regarding issues addressed within the comment and corrective action section of the report. Weeds and stained soils associated with a separate corrective action.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed: _____

Title: EHS

Date: 8/16/2022 2:47:30 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

| | |
|-----------|--------------------------|
| 403138102 | FIR RESOLUTION SUBMITTED |
|-----------|--------------------------|

Total Attach: 1 Files