

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403136333

Date Received:

08/15/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Romana Cowden

720-951-5895

COGCC.inspections@caerusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696203626

Inspection Date: 05/02/2022

FIR Submit Date: 05/04/2022

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 311692

Location Name: Gardner Federal Number: 28-1 (PC-28) County: _____

Qtrqr: Lot 3 Sec: 28 Twp: 7S Range: 95W Meridian: 6

Latitude: 39.415570 Longitude: -108.003280

FACILITY - API Number: 05-045- -00 Facility ID: 311692

Facility Name: Gardner Federal Number: 28-1 (PC-28)

Qtrqr: Lot 3 Sec: 28 Twp: 7S Range: 95W Meridian: 6

Latitude: 39.415570 Longitude: -108.003280

CORRECTIVE ACTIONS:

1 ☒ CA# 161563

Corrective Action: Inspect, maintain and repair tanks to comply with rule 609.b.

Date: 06/04/2022

Response: CA COMPLETED

Date of Completion: 07/13/2022

Operator Comment: Repaired.

COGCC Decision: Approved pending re-inspection

Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an

COGCC Representative: acknowledgement that the corrective action has been passed. Operator has provided no documentation attached to this resolution to show work has been conducted per corrective action(s). A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

2 ☒ CA# 161564

Corrective Action: Remove and properly dispose of impacted material as E&P waste, and assess the integrity of the liner underlying the tank.

Date: 06/04/2022

Response: CA COMPLETED

Date of Completion: 07/13/2022

Operator Comment: Repaired

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. Operator has provided no documentation attached to this resolution to show work has been conducted per corrective action(s). A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

3 ☒ CA# 161565

Corrective Action: Conduct reclamation and repair degraded areas on the south end of the Location. Implement and maintain long term stormwater and erosion control BMPs to stabilize and protect the slopes in accordance with Rule 1002.f.
Continue to monitor and manage areas until the site receives a passing final inspection.

Date: 06/30/2022

Response: CA COMPLETED

Date of Completion: 06/20/2022

Operator Comment: Reclaimed soil migration, hydro seeded and mulched disturbed area.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. Operator has provided no documentation attached to this resolution to show work has been conducted per corrective action(s). A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

4 ☒ CA# 161566

Corrective Action: Comply with 1002.f; implement temporary stormwater and erosion control BMPs to minimize further erosion and degradation at the slopes on the south end of the Location.

Date: 05/11/2022

Response: CA COMPLETED

Date of Completion: 06/20/2022

Operator Comment: Reclaimed soil migration, hydro seeded and mulched disturbed area.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. Operator has provided no documentation attached to this resolution to show work has been conducted per corrective action(s). A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed: _____

Title: EHS

Date: 8/15/2022 3:00:32 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403136333	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files