

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403141770

Date Received:

08/19/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Kellerby, Shaun

shaun.kellerby@state.co.us

.TEP

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 699804745

Inspection Date: 07/27/2022

FIR Submit Date: 08/03/2022

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 422286

Location Name: Monument Ridge Pad Number: _____ County: _____

Qtrqr: SESE Sec: 18 Twp: 7S Range: 95W Meridian: 6

Latitude: 39.431202 Longitude: -108.033248

FACILITY - API Number: 05-045- -00 Facility ID: 422286

Facility Name: Monument Ridge Pad Number: _____

Qtrqr: SESE Sec: 18 Twp: 7S Range: 95W Meridian: 6

Latitude: 39.431202 Longitude: -108.033248

CORRECTIVE ACTIONS:

1 ☒ CA# 163721

Corrective Action: The storage of equipment not necessary for use on location is prohibited.

Date: 08/08/2022

Response: CA COMPLETED

Date of Completion: 08/10/2022

Operator Comment: unused equipment unnecessary for operations has been removed

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 163722

Corrective Action: Remove and properly dispose of stained gavel.

Date: 08/08/2022

Response: CA COMPLETED

Date of Completion: 08/11/2022

Operator
Comment: Stained soils have been removed and residual fluids on the tank washed off

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 ☒ CA# 163723

Corrective Action: All loadlines will be bullplugged or capped

Date: 08/08/2022

Response: CA COMPLETED

Date of Completion: 08/10/2022

Operator
Comment: A bullplug has been installed in all lines regulated under COGCC Rule 603.i

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

4 ☒ CA# 163724

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations.

Date: 08/15/2022

Response: CA COMPLETED

Date of Completion: 08/10/2022

Operator
Comment: BMP's have been implemented to prevent and control rilling and erosion. Area with rilling has been address

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA's 1-4 have been completed

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Kris Rowe

Signed:

Title: TEP Env.

Date: 8/19/2022 10:53:38 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403141770	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files