

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403100530

Date Received:
07/11/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Labowskie, Steve

steve.labowskie@state.co.us

.General

FarmingtonRegulatoryTechs@hilcorp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 702500164

Inspection Date: 07/01/2022

FIR Submit Date: 07/05/2022

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 326147

Location Name: HUBER-LOBATO-N35N8W Number: 26SENW County: LA PLATA

Qtrqtr: SENW Sec: 26 Twp: 35N Range: 8W Meridian: N

Latitude: 37.276070 Longitude: -107.716310

FACILITY - API Number: 05-067- -00 Facility ID: 215946

Facility Name: HUBER-LOBATO Number: 1-26

Qtrqtr: SENW Sec: 26 Twp: 35N Range: 8W Meridian: N

Latitude: 37.276070 Longitude: -107.716310

CORRECTIVE ACTIONS:

1 ☒ CA# 163066

Corrective Action: Remove impacted material and dispose of in approved manner per rule 906 and 1002.f.

Date: 07/19/2022

Response: CA COMPLETED

Date of Completion: 07/08/2022

Operator Comment: We remove and replaced all impacted soil as well as removed all illegally dumped construction debris on fill slope.

COGCC Decision: Approved pending re-inspection

COGCC Representative: CA from previous inspection Doc# 702500164 has been satisfactorily completed.

2 ☒ CA# 163067

Corrective Action: Use or remove unused equipment per rule 606.

Date: 07/19/2022

Response: CA COMPLETED

Date of Completion: 07/08/2022

Operator Comment: All unused equipment and trash around the pump jack and location was hauled off.

COGCC Decision: Approved pending re-inspection

COGCC Representative: CA from previous inspection Doc# 702500164 has been satisfactorily completed.

3 ☒ CA# 163068

Corrective Action: Remove debris per rule 606.

Date: 07/19/2022

Response: CA COMPLETED

Date of Completion: 07/08/2022

Operator Comment: We remove and replaced all impacted soil as well as removed all illegally dumped construction debris on fill slope. All unused equipment and trash around the pump jack and location was hauled off.

COGCC Decision: Approved pending re-inspection

COGCC Representative: CA from previous inspection Doc# 702500164 has been satisfactorily completed.

4 ☒ CA# 163069

Corrective Action: Remove trash to comply with rule 606.

Date: 07/12/2022

Response: CA COMPLETED

Date of Completion: 07/08/2022

Operator Comment: We remove and replaced all impacted soil as well as removed all illegally dumped construction debris on fill slope. All unused equipment and trash around the pump jack and location was hauled off.

COGCC Decision: Approved pending re-inspection

COGCC Representative: CA from previous inspection Doc# 702500164 has been satisfactorily completed.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed:

Title: OperationsRegulatory Tech

Date: 7/11/2022 6:04:30 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number Description

403100530	FIR RESOLUTION SUBMITTED
-----------	--------------------------

403100532	Huber-Lobato 1-26_Resolved Photos
-----------	-----------------------------------

Total Attach: 2 Files