

Inspection Photos and Issue Report

8/25/2022

Operator: LOCIN OIL CORPORATION - 51130

Location #322339

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LOCIN OIL CORPORATION - 51130
Location #322339



Photo 1: Photos provide an overview of the Location.

Inspection Photos
Operator Name: LOCIN OIL CORPORATION - 51130
Location #322339



Photo 2: Signage at well head shows Foundation Energy Management. Records shows Locin Oil Corp as Operator, effective 3/1/2022.

Inspection Photos
Operator Name: LOCIN OIL CORPORATION - 51130
Location #322339



Photo 3: Photo example showing weed establishment on the Location.

Inspection Photos
Operator Name: LOCIN OIL CORPORATION - 51130
Location #322339



Photo 4: Photo example showing weed establishment on access road.

Inspection Photos
Operator Name: LOCIN OIL CORPORATION - 51130
Location #322339



Photo 5: Photos 5-10 taken along the access road between the Government #1 and Government #2 Locations. Photos examples showing erosion control and stabilization BMPs are missing or insufficient along entire access road-erosion degradation and sediment transport evident.

Inspection Photos
Operator Name: LOCIN OIL CORPORATION - 51130
Location #322339



Photo 6: See comments under photo 5.

Inspection Photos
Operator Name: LOCIN OIL CORPORATION - 51130
Location #322339



Photo 7: See comments under photo 5.

Inspection Photos
Operator Name: LOCIN OIL CORPORATION - 51130
Location #322339



Photo 8: See comments under photo 5.

Inspection Photos
Operator Name: LOCIN OIL CORPORATION - 51130
Location #322339



August 25, 2022

Photo 9: See comments under photo 5.

Inspection Photos
Operator Name: LOCIN OIL CORPORATION - 51130
Location #322339



August 25, 2022

Photo 10: See comments under photo 5.

Inspection Photos
Operator Name: LOCIN OIL CORPORATION - 51130
Location #322339



Photo 11: See comments under photo 5.

Inspection Photos
Operator Name: LOCIN OIL CORPORATION - 51130
Location #322339



Photo 12: Photo taken from the access road south of Utah Gas Corp's Federal-Carbonera 1-2; access road is shared between the two Operators. Photo example showing erosion control and stabilization BMPs are missing or insufficient along entire access road- erosion degradation and sediment transport evident.

Inspection Photos
Operator Name: LOCIN OIL CORPORATION - 51130
Location #322339



Photo 13: Continued from photo 12. Hard hat in photo for scale/reference.