

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/24/2022

Submitted Date:

08/30/2022

Document Number:

694500505**FIELD INSPECTION FORM**Loc ID 316755 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10469Name of Operator: ENERGY INVESTMENTS INCAddress: 11164 BEATRICE COURTCity: LITTLETON State: CO Zip: 80125**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ann Miller		ann@energy-investments.com	
O'Malley, Anna		anna.omalley@state.co.us	

General Comment:

on 8/24/2022 COGCC staff, Kris Neidel was present to observe sampling at the Tow Creek well for REM #24468 and Rule 911 compliance. The weather was sunny and 78 degrees. Energy Investments representative, Jim Dschaak was present to collect soil and water samples per Remediation project. At the time of sampling AGT's were still on location. Foam from the Production tanks has blown around the location, in a thousand pieces. Corrective Actions: remove all trash, Gravel and all of the Foam (from tanks), results from sampling should be submitted on a Form 27. See attached photos for details.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	DEBRIS		
Comment:	Gravel that was used during production is still present on pad.		
Corrective Action:	Remove all gravel.	Date:	09/06/2022
Type	TRASH		
Comment:	various types of trash around location from lack of proper housekeeping.		
Corrective Action:	Remove all trash.	Date:	09/06/2022
Type	TRASH		
Comment:	Foam from the production tanks has been spread all around the location and blown off the location		
Corrective Action:	Every piece of this foam should be picked up, this will require some time to remove all of the foam, this is the expectation.	Date:	09/06/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500506	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5843629