

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/26/2022

Submitted Date:

08/26/2022

Document Number:

693507815

FIELD INSPECTION FORMLoc ID 474767 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10651

Name of Operator: VERDAD RESOURCES LLC

Address: 1125 17TH STREET SUITE 550

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
BEECHERL, ARTHUR	214-728-1840	Regulatory@verdadoil.com	all inspections
Cugnetti, Mike		Mcugnetti@verdadoil.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
477665	WELL	PR	06/01/2022	OW	123-51164	County Line 3130-04H	PR

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	DRILLING/RECOMP		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Tracking Pad	In Process			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Inspection due to noise complaints. Spoke with supervisor Brian Stanley he stated site had got shut in due to O2 from trucks unloading tanks. Operator purged lines to bring site on line again. ECD was ran to purge lines and did create noise in complaints. Operator is working on issue to stop issue from occuring again.	silverr	08/26/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693507816	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5844542